



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S
Colour	Blue
Year of manufacture	2003
Top speed	118 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-15
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-03-17
MOT pass rate	95 %
MOT passed	18
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #19 2023-03-01 10:07

MOT test number 974059967512

Result ✓ Passed

Next expiry date 2024-03-17

Minor Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both sides (2.1.3 (g) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened all round (1.1.14 (a) (ii))

MOT #18 2022-02-21 10:15

MOT test number 152362767032

Result ✓ Passed

MOT #17 2021-03-12 15:20

MOT test number 811294116704

Result ✓ Passed

Advice Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))



MOT #16	2020-03-13 12:32
----------------	------------------

MOT test number	669071954353
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #15	2019-03-14 13:14
----------------	------------------

MOT test number	869670922933
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
---------------	---

Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
---------------	--

MOT #14	2018-03-09 12:14
----------------	------------------

MOT test number	141361131593
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2017-03-08 11:48
----------------	------------------

MOT test number	443927508954
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2016-03-10 12:09
----------------	------------------

MOT test number	203914954715
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #11	2015-03-18 09:56
----------------	------------------

MOT test number	547857375009
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2014-02-28 12:35
----------------	------------------

MOT test number	349549954068
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #9	2013-03-28 12:32
---------------	------------------

MOT test number	888107483036
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2012-03-10 09:59
---------------	------------------

MOT test number	528460272028
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Rear Brake pad(s) wearing thin (3.5.1g)
---------------	---

MOT #7	2011-03-16 12:49
---------------	------------------

MOT test number	495365971070
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2011-03-16 12:49
---------------	------------------

MOT test number	638755871022
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	--

MOT #5	2010-03-16 15:21
---------------	------------------

MOT test number	651665870097
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-03-19 13:51
---------------	------------------

MOT test number	302898779090
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-03-28 13:20
---------------	------------------

MOT test number	850018388050
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #2	2007-03-20 13:23
MOT test number	430719777092
Result	✓ Passed
MOT #1	2006-03-21 07:58
MOT test number	220109676047
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
27 March 2023

X

MOT

Expired:
17 March 2024

Tax status	Expired at 27 March 2023
Days left	398 days too late
MOT expiry date	17 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-03-31
Last registration	2023-03-01
Complete history	See info



Registration #1	2003-03-31	7 mi
Registration #2	2006-03-21	19.989 mi
Registration #3	2007-03-20	25.829 mi
Registration #4	2008-03-28	30.780 mi
Registration #5	2009-03-19	35.591 mi
Registration #6	2010-03-16	39.567 mi
Registration #7	2011-03-16	42.756 mi
Registration #8	2012-03-10	45.702 mi
Registration #9	2013-03-28	48.354 mi
Registration #10	2014-02-28	50.472 mi
Registration #11	2015-03-20	52.591 mi
Registration #12	2016-03-20	54.710 mi
Registration #13	2017-03-20	56.829 mi
Registration #14	2018-03-20	58.948 mi
Registration #15	2019-03-20	61.067 mi
Registration #16	2020-03-20	63.186 mi
Registration #17	2021-03-20	65.305 mi
Registration #18	2022-03-20	67.424 mi
Registration #19	2023-03-01	69.543 mi
Registration #20	2023-03-01	71.662 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1716 mm
Height	1422 mm
Length	4516 mm
Wheel base	2562 mm
Kerb weight	1255 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	B4162980778