



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE R-DESIGN
Colour	Red
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 2



Date	2021-07-15
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-01
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-05-11
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	5
Total items failed	4

MOT #13	2023-05-04 13:14
MOT test number	975268108095
Result	✓ Passed
Next expiry date	2024-05-11
Minor	Offside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #12	2023-05-04 09:33
MOT test number	440194135469
Result	✗ Failed
MAJOR	Offside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
Minor	Offside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #11	2022-05-12 15:47
MOT test number	862119410411
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge close on inner edge (5.2.3 (e))
Advice	Exhaust heat shields insecure

MOT #10	2021-01-04 15:49
MOT test number	483015568176
Result	✓ Passed



MOT #9	2019-11-21 11:04
MOT test number	361196819895
Result	✓ Passed
MOT #8	2018-11-12 09:36
MOT test number	574190313296
Result	✓ Passed
MOT #7	2017-11-14 12:21
MOT test number	839847842809
Result	✓ Passed
MOT #6	2016-11-23 09:58
MOT test number	577847284509
Result	✓ Passed
MOT #5	2015-11-23 10:20
MOT test number	224896402023
Result	✓ Passed
MOT #4	2014-12-04 12:32
MOT test number	405108234335
Result	✓ Passed
MOT #3	2013-12-12 14:04
MOT test number	358256643352
Result	✓ Passed



MOT #2	2013-12-11 15:14
MOT test number	635365643395
Result	✗ Failed
Pass with rectification	Offside Rear Rear position lamp(s) not working (1.1.A.3b)
Fail	Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
Pass with rectification	Nearside Rear Rear position lamp(s) not working (1.1.A.3b)
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2012-10-22 10:03
MOT test number	718966692257
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
11 May 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	11 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-29
Last registration	2023-05-04
Complete history	See info



Registration #1	2009-10-29	11 mi
Registration #2	2012-10-22	60.502 mi
Registration #3	2013-12-11	68.959 mi
Registration #4	2013-12-12	68.959 mi
Registration #5	2014-12-04	78.651 mi
Registration #6	2015-11-23	89.707 mi
Registration #7	2016-11-23	100.157 mi
Registration #8	2017-11-14	110.366 mi
Registration #9	2018-05-29	121.277 mi
Registration #10	2019-05-29	131.277 mi
Registration #11	2020-05-29	141.277 mi
Registration #12	2021-05-29	151.277 mi
Registration #13	2022-05-29	161.277 mi
Registration #14	2023-05-29	171.277 mi
Registration #15	2024-05-29	181.277 mi
Registration #16	2025-05-29	191.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	704037