





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE TSI
Colour	White
Year of manufacture	2015
Top speed	114 mph
0 - 100 km/h	10.8 seconds
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	160 Nm at 1.400 rpm
Engine capacity	1.197 сс
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/11



SC65KCK report date: 2024-03-28


Internet history

Entry 1

Date 2021-08-04

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-09
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #8	2023-08-10 11:50
MOT test number	675698670523
Result	✓ Passed
Next expiry date	2024-08-09

MOT #7	2022-07-26 13:36
MOT test number	821893392168
Result	✓ Passed
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	

MOT #6	2022-07-26 10:12
MOT test number	673544282166
Result	× Failed
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Fail Offside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))	

MOT #5	2021-07-26 15:27
MOT test number	241069312017
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2020-11-05 15:42 **MOT** test number 387153797062 Result ✓ Passed **Advice** Offside Front Service brake binding but not excessively (1.2.1 (f)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice**

MOT #3

MOT test number

Fesult

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #2
 2018-11-24 11:14

 MOT test number
 835217585497

 Result
 ✓ Passed

MOT #1 2018-11-24 09:56
MOT test number 703868088385

Result × Failed

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Date

Damage 2

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	hictor,
UWNEI	nisioiv
OWINCE	THISCOLY

Owner History	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	UK AZ
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-11-27
Last registration	2023-08-10
Complete history	See info



Registration #1	2015-11-27	23 mi
Registration #2	2018-11-24	9.584 mi
Registration #3	2018-11-24	9.584 mi
Registration #4	2019-11-21	12.379 mi
Registration #5	2020-11-05	14.470 mi
Registration #6		71.777 es
Registration #6 Registration #7		11.00 m
•		11.77 m
Registration #7		11.77 es 11.77 es 11.77 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1901 mm
Height	1462 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1007 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack caluk	nago 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	CJZC437240