



report date: 2024-03-29

General information

Make	FIAT
Model	BRAVO DYNAMIC
Colour	Black
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	128 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-06
Pictures	12
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #15	2021-11-22 13:57
MOT test number	695245794313
Result	✓ Passed
Next expiry date	2022-12-02
Advice	Reverse lamp inoperative
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14	2021-11-19 10:04
MOT test number	764025290052
Result	✗ Failed
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Windscreen washer not working (3.5 (a))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Emissions not tested (8.2.1.2 (d))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Exhaust has a major leak of exhaust gases front flexi (6.1.2 (a))
Advice	Reverse lamp inoperative
Fail	Nearside Rear Outer Tyre has ply or cords exposed wall 205/55/16v (5.2.3 (d) (ii))

MOT #13	2020-12-03 11:58
MOT test number	731521108165
Result	✓ Passed

**MOT #12** 2019-08-29 08:04**MOT test number** 738997564567**Result** ✓ Passed**Advice** Nearside Front tyre cracks around tread area**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing and cracks around tread area/nail in tyre (5.2.3 (d) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front tyre cracks around tread area**MOT #11** 2018-08-20 08:40**MOT test number** 370808943820**Result** ✓ Passed**Advice** Rear exhaust box outre skin corroded**MOT #10** 2018-08-20 08:40**MOT test number** 158201192209**Result** ✗ Failed**Advice** Rear exhaust box outre skin corroded**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #9** 2017-08-14 15:56**MOT test number** 469400580873**Result** ✓ Passed**MOT #8** 2017-08-14 10:41**MOT test number** 276121597312**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #7** 2016-08-15 09:27**MOT test number** 835277499631**Result** ✓ Passed**Advice** Front brake discs slightly lipped**Advice** Front brake pads wearing half way**Advice** Exhaust system has slight leak**MOT #6** 2015-08-24 08:45**MOT test number** 572174511223**Result** ✓ Passed**MOT #5** 2014-08-29 12:42**MOT test number** 419791744280**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2013-08-23 09:31**MOT test number** 955925233294**Result** ✓ Passed**MOT #3** 2013-08-23 09:31**MOT test number** 328975233479**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #2** 2012-08-28 10:41**MOT test number** 819491042215**Result** ✓ Passed



MOT #1	2012-03-06 12:35
MOT test number	319476562061
Result	✓ Passed



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-04-21
Last registration	2021-11-22
Complete history	See info



Registration #1	2009-04-21	11 mi
Registration #2	2012-03-06	14.285 mi
Registration #3	2012-08-28	15.023 mi
Registration #4	2013-08-23	19.267 mi
Registration #5	2014-08-29	24.358 mi
Registration #6	2015-08-24	31.100 mi
Registration #7	2016-08-15	36.336 mi
Registration #8	2017-08-14	43.315 mi
Registration #9	2018-08-14	50.294 mi
Registration #10	2019-08-14	57.273 mi
Registration #11	2020-08-14	64.252 mi
Registration #12	2021-08-14	71.231 mi
Registration #13	2022-08-14	78.210 mi
Registration #14	2023-08-14	85.189 mi
Registration #15	2024-03-29	92.168 mi
Registration #16	2024-03-29	99.147 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1307868