




report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO SOUND
Colour	Black
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg





Internet history

Entry 1

Date	2021-10-26
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #13	2021-10-22 14:05
MOT test number	419330105530
Result	✓ Passed
Next expiry date	2022-11-19
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
Advice	Front both font tyres won ,inner edges

MOT #12	2020-10-26 15:01
MOT test number	185927454867
Result	✓ Passed

MOT #11	2020-10-26 13:21
MOT test number	448676185191
Result	✗ Failed
MAJOR	Horn not working (7.7 (a) (ii))
MAJOR	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
MAJOR	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #10	2019-10-29 10:24
MOT test number	358890657076
Result	✓ Passed
Advice	Exhaust rusting

MOT #9	2018-10-24 13:38
MOT test number	148520112839
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))



MOT #8	2018-10-23 10:44
MOT test number	187615220769
Result	✗ Failed
MAJOR	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
MAJOR	Emissions not tested engine miss firing (8.2.1.2 (d))
MAJOR	Offside Headlamp aim too high (4.1.2 (a))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #7	2017-11-10 15:24
MOT test number	163584620935
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #6	2016-11-15 17:08
MOT test number	574769892678
Result	✓ Passed

MOT #5	2016-11-15 14:26
MOT test number	848024109132
Result	✗ Failed
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



MOT #4	2015-10-29 13:15
MOT test number	675433727680
Result	✓ Passed
Advice	Tyre worn close to the legal limit both front (4.1.E.1)

MOT #3	2014-11-20 09:29
MOT test number	537354724372
Result	✓ Passed
Notice	Nail in nearside rear tyre

MOT #2	2013-11-06 09:25
MOT test number	966770613335
Result	✓ Passed

MOT #1	2012-11-19 13:02
MOT test number	306734022337
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	VK10UVZ
Plate since	2019-09-29
Current registration	VK10UVZ
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-05-16
Last registration	2021-10-22
Complete history	See info



Registration #1	2010-05-16	16 mi
Registration #2	2012-11-19	20.778 mi
Registration #3	2013-11-06	32.273 mi
Registration #4	2014-11-20	42.061 mi
Registration #5	2015-10-29	49.860 mi
Registration #6	2016-11-15	57.559 mi
Registration #7	2016-11-15	57.559 mi
Registration #8	2017-11-10	71.473 mi
Registration #9	2019-05-22	85.377 mi
Registration #10	2019-05-22	85.377 mi
Registration #11	2019-05-22	85.377 mi
Registration #12	2019-05-22	85.377 mi
Registration #13	2019-05-22	85.377 mi
Registration #14	2019-05-22	85.377 mi
Registration #15	2021-10-22	100.000 mi

[More info >](#)



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9632561