



**LRI2XJY**

report date: 2024-03-28

General information

Make	KIA
Model	RIO CRDI 2 ECODYNAMICS
Colour	White
Year of manufacture	2012
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B





## MOT history

MOT expiry date	2024-10-28
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	35
Total items failed	9

MOT #14	2023-10-27 12:45
MOT test number	462098728259
Result	✓ Passed
Next expiry date	2024-10-28
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-10-22 12:08
MOT test number	599218529385
Result	✓ Passed
Advice	Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

MOT #12	2021-10-29 13:31
MOT test number	646151089330
Result	✓ Passed

MOT #11	2020-08-14 13:06
MOT test number	449426592421
Result	✓ Passed
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #10**

2020-08-05 12:19

**MOT test number**

908985267433

**Result****✗ Failed**

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #9**

2019-08-20 16:05

**MOT test number**

851329840660

**Result****✓ Passed**

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #8**

2019-08-09 09:59

**MOT test number**

290181092543

**Result****✗ Failed**

**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Fail** Offside Side repeater not working (4.4.1 (a) (ii))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #7** 2018-08-15 10:09**MOT test number** 223449294755**Result** ✓ Passed

**Minor** Offside Windscreen damaged but not adversely affecting driver's view damage contained within 10mm (3.2 (a) (i))

**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect has limited damping effect (5.3.2 (b))

**MOT #6** 2018-08-15 09:39**MOT test number** 101319206199**Result** ✗ Failed

**Fail** Offside Headlamp light intensity severely reduced dipped beam (4.1.4 (a))

**Minor** Offside Windscreen damaged but not adversely affecting driver's view damage contained within 10mm (3.2 (a) (i))

**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect has limited damping effect (5.3.2 (b))

**MOT #5** 2017-08-03 08:57**MOT test number** 577133220394**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

**MOT #4** 2017-08-03 08:57**MOT test number** 614334489066**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2016-08-03 15:57**MOT test number** 304598573451**Result** ✓ Passed**MOT #2** 2015-08-05 10:21**MOT test number** 858317615217**Result** ✓ Passed**Notice** O/S/R parking brake lazy**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Notice** Front wipers starting to smear**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #1 2015-08-05 10:21

MOT test number 116337315222

Result ✗ Failed

**Notice** Front wipers starting to smear

**Pass with rectification** Nearside Headlamp aim too low (1.8)

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Notice** O/S/R parking brake lazy

**Notice** Vehicle's internal headlight adjuster altered to recheck lights

**Pass with rectification** Offside Headlamp aim too low (1.8)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
28 October 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	28 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-




Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>LR12XJY</b>
Plate since	2019-03-28
Current registration	<b>LR12XJY</b>
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-09
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2012-03-09	7 mi
Registration #2	2015-08-05	25.446 mi
Registration #3	2016-08-03	41.608 mi
Registration #4	2017-08-03	52.841 mi
Registration #5	2017-08-03	52.841 mi
Registration #6	2018-08-15	58.661 mi
Registration #7	2018-08-15	58.661 mi
Registration #8	2019-05-29	59.377 mi
Registration #9	2019-05-29	59.377 mi
Registration #10	2019-05-29	59.377 mi
Registration #11	2019-05-29	59.377 mi
Registration #12	2019-05-29	59.377 mi
Registration #13	2019-05-29	59.377 mi
Registration #14	2019-05-29	59.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1341 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FCBH004881