




report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D5 SE AWD
Colour	Grey
Year of manufacture	2009
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J






Internet history

Entry 1

Date	2022-02-28
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-26
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	4
Total items failed	2

MOT #12	2023-01-27 08:19
MOT test number	149286019134
Result	✓ Passed
Next expiry date	2024-01-26

MOT #11	2023-01-24 11:34
MOT test number	175285538895
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #10	2021-09-20 13:18
MOT test number	549675724942
Result	✓ Passed

MOT #9	2020-09-23 17:12
MOT test number	814513495503
Result	✓ Passed

MOT #8	2019-09-03 11:31
MOT test number	688714575908
Result	✓ Passed

**MOT #7** 2018-09-12 16:02**MOT test number** 280432354700**Result** ✓ Passed**MOT #6** 2017-09-19 09:11**MOT test number** 112118908636**Result** ✓ Passed**MOT #5** 2016-09-19 10:36**MOT test number** 215548171615**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2015-09-08 15:21**MOT test number** 140043604046**Result** ✓ Passed**MOT #3** 2014-09-23 09:44**MOT test number** 495386764206**Result** ✓ Passed**MOT #2** 2013-09-26 10:44**MOT test number** 287579763217**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #1	2012-09-27 13:24
MOT test number	866141372295
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2023

X

MOT

Expired:
26 January 2024

Tax status	Expired at 1 March 2023
Days left	424 days too late
MOT expiry date	26 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	NL59XXC
Plate since	2019-03-29
Current registration	NL59XXC
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-09-30
Last registration	2023-01-27
Complete history	See info



Registration #1	2009-09-30	11 mi
Registration #2	2012-09-27	31.824 mi
Registration #3	2013-09-26	42.066 mi
Registration #4	2014-09-23	50.069 mi
Registration #5	2015-09-08	59.093 mi
Registration #6	2016-09-19	69.207 mi
Registration #7	2017-09-19	75.995 mi
Registration #8	2018-09-19	75.995 mi
Registration #9	2019-09-19	75.995 mi
Registration #10	2020-09-19	75.995 mi
Registration #11	2021-09-19	75.995 mi
Registration #12	2022-09-19	75.995 mi
Registration #13	2023-01-27	75.995 mi
Registration #14	2023-01-27	75.995 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1863 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	745321