



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 AUTHORITIES
Colour	Silver
Year of manufacture	2012
Top speed	137 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-24
Pictures	2
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-12-06
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	18
Total items failed	3

MOT #13 2023-12-06 10:01

MOT test number 947584398500

Result ✓ Passed

Next expiry date 2024-12-06

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12 2022-12-02 09:57

MOT test number 646865591585

Result ✓ Passed

**Advice** Tyre worn close to legal limit/worn on edge all tyres (5.2.3 (e))

MOT #11 2022-12-02 09:57

MOT test number 432414779764

Result ✗ Failed

**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))

**Advice** Tyre worn close to legal limit/worn on edge all tyres (5.2.3 (e))

**MOT #10** 2021-12-07 13:55**MOT test number** 117044889187**Result** ✓ Passed**MOT #9** 2021-12-04 10:45**MOT test number** 440817623247**Result** ✗ Failed**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #8** 2021-01-19 16:15**MOT test number** 474632896698**Result** ✓ Passed**MOT #7** 2020-01-10 10:37**MOT test number** 132934315418**Result** ✓ Passed**MOT #6** 2019-01-15 11:31**MOT test number** 239589668484**Result** ✓ Passed**Advice** Under-trays fitted obscuring some underside components**Advice** Emissions not detected by smoke machine, could not register the reading**Advice** Brake wear light illuminated**Advice** Engine covers fitted obscuring some components in the engine bay**Advice** Unable to inspect/access trailer electrical socket**Minor** Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))

**MOT #5** 2019-01-15 11:31**MOT test number** 786423788797**Result** ✗ Failed

- Advice** Under-trays fitted obscuring some underside components
- Minor** Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))
- Advice** Emissions not detected by smoke machine, could not register the reading
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Brake wear light illuminated
- Advice** Engine covers fitted obscuring some components in the engine bay
- Advice** Unable to inspect/access trailer electrical socket

**MOT #4** 2018-01-05 12:23**MOT test number** 792030138759**Result** ✓ Passed**MOT #3** 2017-01-13 13:41**MOT test number** 953398230871**Result** ✓ Passed**MOT #2** 2016-03-11 14:51**MOT test number** 313853825206**Result** ✓ Passed**MOT #1** 2015-03-20 10:11**MOT test number** 587419775030**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
6 December 2024

Tax status		Valid until 1 December
Days left		217
MOT expiry date		6 December 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-04-16
Last registration	2023-12-06
Complete history	<a href="#">See info</a>



Registration #1	2012-04-16	18 mi
Registration #2	2015-03-20	44.391 mi
Registration #3	2016-03-11	57.969 mi
Registration #4	2017-01-13	68.316 mi
Registration #5	2018-01-05	81.296 mi
Registration #6	2019-01-15	95.352 mi
Registration #7	2019-01-15	95.352 mi
Registration #8	2020-01-10	108.991 mi
Registration #9	2020-01-10	108.991 mi
Registration #10	2020-01-10	108.991 mi
Registration #11	2020-01-10	108.991 mi
Registration #12	2020-01-10	108.991 mi
Registration #13	2020-01-10	108.991 mi
Registration #14	2020-01-10	108.991 mi
Registration #15	2020-01-10	108.991 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm

Additional information

Number of seats	5
Number of axles	2
Engine number	1091388