



report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO 625 ENTERPRISE L1 HDI
Colour	White
Year of manufacture	2016
Top speed	94 mph
0 - 60 mph	16.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	185 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-01-22
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	14
Total items failed	10

MOT #7	2023-01-23 14:41
MOT test number	323690634778
Result	✓ Passed
Next expiry date	2024-01-22

MOT #6	2023-01-23 14:41
MOT test number	737655872848
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #5	2021-12-10 14:41
MOT test number	707049598506
Result	✓ Passed

MOT #4	2020-11-19 08:38
MOT test number	578808103659
Result	✓ Passed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #3**

2020-11-18 08:56

MOT test number

725743467768

Result**✗ Failed**

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Spare wheel carrier insecure (6.1.5 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear All direction indicators slightly discoloured (4.4.3 (a))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2

2019-05-29 08:22

MOT test number

880970956769

Result**✓ Passed**

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #1	2019-05-28 09:56
MOT test number	469606488421
Result	✗ Failed
Fail	Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Front tyre valve is not located in the hub cap
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



Tax & MOT check

X

Untaxed

Tax expired:
1 January 2023

X

MOT

Expired:
22 January 2024

Tax status	Expired at 1 January 2023
Days left	484 days too late
MOT expiry date	22 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-06-02
Last registration	2023-01-23
Complete history	See info



Registration #1	2016-06-02	25 mi
Registration #2	2019-05-28	120.574 mi
Registration #3	2019-05-29	120.574 mi
Registration #4	2020-11-18	164.926 mi
Registration #5	2020-11-19	164.926 mi
Registration #6	2022-05-20	25,277 mi
Registration #7	2022-05-20	25,277 mi
Registration #8	2022-05-20	25,277 mi
Registration #9	2022-05-20	25,277 mi

More info >



Safety ratings

NCAP rating	★★★★☆	▢
Adult	56%	
Children	74%	
Pedestrian	63%	
Safety systems	48%	
Overall rating	59%	
Video	see crash video	

Dimensions & weight

Width	2112 mm
Height	1801 mm
Length	4380 mm
Kerb weight	1304 kg
Max. allowed weight	1945 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBEM0517504