



report date: 2024-03-28

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Silver
Year of manufacture	2008
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-08-31
Pictures	12
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-10-04
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	27
Total items failed	5

MOT #20 2023-10-02 13:30

MOT test number 261756813892

Result ✓ Passed

Next expiry date 2024-10-04

Advice Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Front Brake disc corrosion both sides .

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19 2023-10-02 11:01

MOT test number 514604103552

Result ✗ Failed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Front Brake disc corrosion both sides .

MAJOR Horn not working (7.7 (a))

Advice Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #18 2022-09-30 14:46

MOT test number 932063217414

Result ✓ Passed

**MOT #17** 2022-09-30 09:58**MOT test number** 870826137396**Result** ✗ Failed**MAJOR** Horn not working (7.7 (a))**MOT #16** 2021-10-05 10:30**MOT test number** 866308911615**Result** ✓ Passed**MOT #15** 2021-09-27 13:39**MOT test number** 232883094922**Result** ✗ Failed**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))**MOT #14** 2020-08-21 12:20**MOT test number** 616015394050**Result** ✓ Passed**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Exhaust overall condition starting to deteriorate**MOT #13** 2020-08-20 14:44**MOT test number** 122783030428**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Exhaust overall condition starting to deteriorate**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #12** 2019-08-13 09:26**MOT test number** 413364571118**Result** ✓ Passed**MOT #11** 2018-08-10 16:45**MOT test number** 994736737683**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #10** 2018-08-10 11:13**MOT test number** 681266240568**Result** ✗ Failed**MAJOR** Horn not working (7.7 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #9** 2017-08-24 10:53**MOT test number** 901298487349**Result** ✓ Passed**MOT #8** 2017-08-16 08:32**MOT test number** 992178899318**Result** ✗ Failed**Fail** Horn not working (1.6.2a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2017-02-24 12:18**MOT test number** 768812324357**Result** ✓ Passed**MOT #6** 2016-03-07 15:13**MOT test number** 821601018315**Result** ✓ Passed**MOT #5** 2016-03-07 09:39**MOT test number** 343678217267**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Offside Rear Tyre heavily deteriorated and punctured.**Advice** Offside Front Tyre slightly deteriorated.**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre deteriorated.**MOT #4** 2015-03-11 09:24**MOT test number** 409690075031**Result** ✓ Passed**MOT #3** 2013-10-26 13:15**MOT test number** 219229393242**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2012-10-31 12:10
MOT test number	758545202398
Result	✓ Passed
MOT #1	2011-10-25 12:47
MOT test number	937698991243
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
4 October 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	ND58UAO
Plate since	2019-03-28
Current registration	ND58UAO
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-10-31
Last registration	2023-10-02
Complete history	See info



Registration #1	2008-10-31	17 mi
Registration #2	2011-10-25	18.765 mi
Registration #3	2012-10-31	23.163 mi
Registration #4	2013-10-26	26.927 mi
Registration #5	2015-03-11	30.246 mi
Registration #6	2016-03-07	36.794 mi
Registration #7	2016-03-07	36.794 mi
Registration #8	2017-02-24	41.701 mi
Registration #9	2017-08-16	45.262 mi
Registration #10	2017-08-24	45.262 mi
Registration #11	2018-08-10	50.790 mi
Registration #12	2019-08-20	55.317 mi
Registration #13	2020-08-20	55.317 mi
Registration #14	2021-08-20	55.317 mi
Registration #15	2022-08-20	55.317 mi
Registration #16	2023-08-20	55.317 mi
Registration #17	2023-08-20	55.317 mi
Registration #18	2023-08-20	55.317 mi
Registration #19	2023-08-20	55.317 mi
Registration #20	2023-08-20	55.317 mi
Registration #21	2023-08-20	55.317 mi
Registration #22	2023-08-20	55.317 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1082 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8K72026