



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE CDTi
Colour	White
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	27.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	36.2 mpg
CO2 emission	205 g/km
CO2 label	K





MOT history

MOT expiry date	2025-04-25
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	20
Total items failed	4

MOT #12 2024-04-26 11:06

MOT test number 419946883574

Result ✓ Passed

Next expiry date 2025-04-25

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2023-03-24 09:30

MOT test number 936911684889

Result ✓ Passed

MOT #10 2023-03-17 11:04

MOT test number 500442756784

Result ✗ Failed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Rear Position lamp lens seriously defective (4.2.1 (b))

Fail Nearside Front Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))

**MOT #9**

2021-08-02 12:22

MOT test number

938156280204

Result

✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge @2mm on inner edge (5.2.3 (e))

MOT #8

2021-08-02 09:33

MOT test number

909181778695

Result

✗ Failed

- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge @2mm on inner edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #7

2020-07-23 09:32

MOT test number

847080674000

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Nail in tyre x2
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #6** 2019-08-02 09:42**MOT test number** 919455935347**Result** ✓ Passed**Advice** Offside Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**MOT #5** 2018-07-27 08:53**MOT test number** 974680925484**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**MOT #4** 2017-08-05 11:59**MOT test number** 173128622006**Result** ✓ Passed**MOT #3** 2016-10-26 13:52**MOT test number** 594512409065**Result** ✓ Passed**MOT #2** 2016-01-11 12:30**MOT test number** 480564748293**Result** ✓ Passed**MOT #1** 2015-02-26 12:44**MOT test number** 286577255014**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
25 April 2025

Tax status	Valid until 1 May
Days left	2
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 LD12VUJ
Plate since	2019-03-28
Current registration	 LD12VUJ
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-04-24
Last registration	2024-04-26
Complete history	See info



Registration #1	2012-04-24	20 mi
Registration #2	2015-02-26	8.234 mi
Registration #3	2016-01-11	11.242 mi
Registration #4	2016-10-26	13.694 mi
Registration #5	2017-08-05	15.363 mi
Registration #6	2018-07-27	25.622 mi
Registration #7	2019-08-02	34.269 mi
Registration #8	2020-05-20	35.277 mi
Registration #9	2021-05-20	35.277 mi
Registration #10	2022-05-20	35.277 mi
Registration #11	2023-05-20	35.277 mi
Registration #12	2024-05-20	35.277 mi
Registration #13	2025-05-20	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1747 mm
Length	4576 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	113063K