





report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CUSTOM 300 BASE P/V L1 H1
Colour	White
Year of manufacture	2018
Top speed	103 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	96 kW / 131 HP / 104 BHP
Max. torque	360 Nm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	44.1 mpg
CO2 emission	167 g/km
CO2 label	Н



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

_				_	-
-	n	т	rv	,	

Date	2021-10-29
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-03-24
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	9
Total items failed	4

MOT #9	2024-03-25 12:01
MOT test number	788755234108
Result	✓ Passed
Next expiry date	2025-03-24
Advice Nearside Non obligatory mirror damaged	

MOT #8	2024-03-25 10:38
MOT test number	890164360157
Result	× Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Advice Nearside Non obligatory mirror damaged	

MOT #7	2024-03-25 10:33
MOT test number	408960403811
Result	✓ Passed
MOT #6	2023-09-04 16:59
MOT test number	918701773357
Result	✓ Passed
Advice Nearside Rear TAIL LIGHT HAS A CRACK	
Advice Nearside Non obligatory mirror damaged	

CarCheck.co.uk page 3/10



report date: 2024-03-28

MOT test number
900368755058

Result
Advice Nearside Rear TAIL LIGHT HAS A CRACK

Fail Offside Side repeater not working (4.4.1 (a) (ii))

Advice Nearside Non obligatory mirror damaged

MOT #4

MOT test number

402530388098

Result

Advice Offside rear tail light cracked (water ingress)

MOT test number

Result

Pass with rectification

Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Offside rear tail light cracked (water ingress)

Pass with rectification

Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #2

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #1
 2021-06-08 11:48

 MOT test number
 564428319734

 Result
 ✓ Passed

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

_	
Owner	nictory
COVITED	11151017
• • • • • • • • • • • • • • • • • • • •	,

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
See in this check if this FOND had different humber plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SILV
Plate since	
	More info >

CarCheck.co.uk page 7/10



MA68MWV

report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2018-09-27
Last registration	2024-03-25
Complete history	See info



Registration #1	2018-09-27	14 mi
Registration #2	2021-06-08	20.362 mi
Registration #3		11.777 es
Registration #4	2022-04-16	27.625 mi
Registration #5	2023-04-01	65.188 mi
Registration #6	2023-04-01	65.188 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2272 mm
Height	2020 mm
Length	4972 mm
Wheel base	2 mm
Kerb weight	1815 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	3 page 10/10

Number of axles 2
Engine number JY11961