





General information

Make	VAUXHALL
Model	AGILA S AC
Colour	Black
Year of manufacture	2013
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	С







Internet history

Entry 2

Date Pictures 2021-12-22

20

Listing price

View report



source: yesauto.com

Entry 1

Date	2021-11-30
Pictures	2
Listing price	<u>View report</u>



source: cargurus.co.uk





MOT history

MOT expiry date	2024-12-22
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	10
Total items failed	3

MOT #10		2023-12-14 11:42
MOT test	number	896440940477
Result		✓ Passed
Next expir	ry date	2024-12-22
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #9	2022-12-01 09:22
MOT test	number 562028239704
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened slightly lipped (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8		2021-12-23 14:25
MOT test	number	771951071462
Result		✓ Passed
Advice (ii))	Rear Tyre slightly damaged/cracking or perishing both show slight cracking	/perishing (5.2.3 (d)
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	





MOT #7	2021-12-21 16:33
MOT test number	813745065160
Result	🗙 Failed
Fail Parking brake lever has excessive movement indicating incorrect adjustment	(1.1.6 (c))
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3)	.4 (b) (ii))
Advice Rear Tyre slightly damaged/cracking or perishing both show slight cracking/perishing (5.2.3 (d) (ii))	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4	(b) (ii))

MOT #6	2021-07-02 08:52
MOT test number	343174103882
Result	✓ Passed
MOT #5	2020-07-10 09:03
MOT test number	248486816195
Result	✓ Passed
MOT #4	2019-07-05 09:01
MOT test number	130521553209
Result	✓ Passed
MOT #3	2018-07-23 09:17
MOT test number	225021382210
Result	✓ Passed
MOT #2	2017-07-31 08:46
	005001010000

MOT test number	895081210363
Result	✓ Passed





MOT #1	2016-08-08 07:56
MOT test number	974099153090
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 22 December 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	22 December 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

AND	

NUMBER OF CONTRACTOR OF CONTRA	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-01
Last registration	2023-12-14
Complete history	<u>See info</u>



Registration #1	2013-09-01	8 mi
Registration #2	2016-08-08	10.264 mi
Registration #3	2017-07-31	12.860 mi
Registration #4	2018-07-23	15.359 mi
Registration #5	2019-07-05	19.832 mi
Registration #6	2020-07-10	21.787 mi
Registration #7	2021-07-02	23.266 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 esi





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1000 kg
Max. allowed weight	1485 kg
Additional information	
Additional information Fuel tank capacity	45 l
	45 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection