





### General information

Make	LAND ROVER
Model	DEFENDER TD XS STATION WAGON
Colour	Black
Year of manufacture	2016
Top speed	90 mph
0 - 60 mph	17.0 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	122 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	4.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	29.1 mpg
Consumption combined	25.5 mpg
CO2 emission	295 g/km
CO2 label	Μ







## Internet history

Entry	3
Date	

Pictures

2022-01-05 23

23

Listing price

View report



source: autotrader.co.uk

#### Entry 2

Date

Pictures

Listing price


24 <u>View report</u>


2021-09-15




#### source: cargurus.co.uk

Entry 1	
Date	2021-09-14
Pictures	34
Listing price	View report









source: autotrader.co.uk



# MOT history

MOT expiry date	2025-04-24
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	10
Total items failed	4

MOT #8	2024-04-25 12:24
MOT test number	946918418710
Result	✓ Passed
Next expiry date	2025-04-24

MOT #7	2023-05-26 15:31
MOT test number	376720020689
Result	✓ Passed
Advice Slight leaking of grease from nsf swivel joint/globe seal	
Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice Engine covers + under trays fitted	
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))	





МОТ #6		2023-04-26 11:49
MOT test number		708559411824
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	
Fail Nearside Rear Anti	-roll bar ball joint dust cover no longer prevents the i	ngress of dirt (5.3.4 (b) (ii))
Minor Nearside Front V	/indscreen wiper blade defective (3.4 (b) (i))	
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	
Fail Nearside Rear Anti	-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Advice Power steering pipe/hose has slight seepage From reservoir pipe (2.1.5 (a))		
Advice Slight weeping of grease from nearside front axle swivel joint (globe seal)		
Minor Offside Front Wi	ndscreen wiper blade defective (3.4 (b) (i))	

MOT #5	2022-05-10 13:50
MOT test number	841967865013
Result	✓ Passed
МОТ #4	2021-04-30 11:01
MOT test number	299186177666
Result	✓ Passed
MOT #3	2020-02-17 12:42
MOT test number	986267561534
Result	✓ Passed





MOT #2	2019-04-08 12:23
MOT test	number 752217251813
Result	✓ Passed
Advice	Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1	2019-01-30 14:09
MOT test number	277793203772
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 June 2024	✓ MOT Expires: 24 April 2025
Tax status	Valid until 1 June
Days left	34
MOT expiry date	24 April 2025
Full MOT history	See MOT history

# Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET I
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Category	AMPL
Туре	

#### Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
*******	
*******	
	More info >
Plate changes	

See in this check if this LAND ROVER had different number plates.



### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-08-18
Last registration	2024-04-25
Complete history	See info



Registration #1	2016-08-18	25 mi
Registration #2	2019-01-30	4 mi
Registration #3	2019-04-08	86 mi
Registration #4	2020-02-17	655 mi
Registration #5	2021-04-30	1.552 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.277 esi

More info >



# Dimensions & weight

Width	1992 mm
Height	2181 mm
Length	4785 mm
Kerb weight	2125 kg
Max. allowed weight	3050 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	18072643334