



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK220 CDI SPORT
Colour	Silver
Year of manufacture	2009
Top speed	137 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-06-19
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	26
Total items failed	13

MOT #17	2023-09-01 08:08
MOT test number	463211248513
Result	✓ Passed
Next expiry date	2024-08-31
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2023-08-24 13:05
MOT test number	236944973614
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15	2022-07-08 10:54
MOT test number	110370143215
Result	✓ Passed
Advice	High level stop lamp not working

**MOT #14**

2022-07-07 16:02

MOT test number

856509039964

Result**✗ Failed****Fail** Rear Stop lamp(s) not working high level (4.3.1 (a) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn Front arm (5.3.4 (a) (i))**Advice** Handbrake imbalanced**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13**

2021-10-22 13:01

MOT test number

884407792043

Result**✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12**

2021-10-11 16:44

MOT test number

973135842727

Result**✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #11** 2020-10-12 13:53**MOT test number** 764054392237**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2019-08-23 15:13**MOT test number** 908744253455**Result** ✓ Passed**MOT #9** 2018-08-28 16:35**MOT test number** 198638034215**Result** ✓ Passed**Advice** Front tyres cracking inner walls**MOT #8** 2017-08-21 15:10**MOT test number** 656069434717**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit 2.6mm (4.1.E.1)**Advice** Nearside Front Tyre has damage to outer wall**MOT #7** 2016-09-02 12:34**MOT test number** 481668142077**Result** ✓ Passed

**MOT #6** 2015-08-07 12:20**MOT test number** 634592677252**Result** ✓ Passed**Advice** Items removed from mirror**MOT #5** 2015-08-06 12:31**MOT test number** 595563201099**Result** ✗ Failed**Advice** Items removed from mirror**Fail** Rear registration plate character(s) laid out in an incorrect format (6.3.4f)**Fail** Front registration plate character(s) laid out in an incorrect format (6.3.4f)**MOT #4** 2014-08-07 18:17**MOT test number** 197309814295**Result** ✓ Passed**MOT #3** 2014-03-08 10:06**MOT test number** 805177564016**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Offside front tyre cut on inner wall**Notice** Nearside front tyre cut on inner wall**MOT #2** 2013-03-12 15:45**MOT test number** 348061373047**Result** ✓ Passed**Notice** Both rear tyres worn on inner edges



MOT #1	2012-03-13 14:12
MOT test number	319033572087
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 KN09HGC
Plate since	2019-09-29
Current registration	 KN09HGC
Plate since	2019-09-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-31
Last registration	2023-09-01
Complete history	See info



Registration #1	2009-03-31	25 mi
Registration #2	2012-03-13	42.601 mi
Registration #3	2013-03-12	55.194 mi
Registration #4	2014-03-08	65.627 mi
Registration #5	2014-08-07	70.548 mi
Registration #6	2015-08-06	73.804 mi
Registration #7	2015-08-07	73.832 mi
Registration #8	2016-09-02	77.591 mi
Registration #9	2017-08-21	81.868 mi
Registration #10	2018-08-28	85.774 mi
Registration #11	2019-09-01	89.680 mi
Registration #12	2020-09-01	93.586 mi
Registration #13	2021-09-01	97.492 mi
Registration #14	2022-09-01	101.398 mi
Registration #15	2023-09-01	105.304 mi
Registration #16	2024-09-01	109.210 mi
Registration #17	2025-09-01	113.116 mi
Registration #18	2026-09-01	117.022 mi
Registration #19	2027-09-01	120.928 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1595 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64696630647009