



PEUGEOT



YS55EUE

report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 HDI SW SE
Colour	Silver
Year of manufacture	2005
Top speed	117 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-15
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-07
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	29
Total items failed	3

MOT #20	2024-01-08 12:08
MOT test number	845406683576
Result	✓ Passed
Next expiry date	2025-01-07

MOT #19	2024-01-04 12:25
MOT test number	802670002298
Result	✗ Failed
MAJOR	Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
MAJOR	Electronic stability control warning lamp indicates a fault (7.12 (e))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Nearside Parking brake inoperative on one side (1.4.1 (a))
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #18	2023-01-05 11:38
MOT test number	951107995772
Result	✓ Passed
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #17** 2022-01-08 09:01**MOT test number** 653745275327**Result** ✓ Passed**MOT #16** 2022-01-05 14:08**MOT test number** 594781025526**Result** ✗ Failed

- MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- DANGEROUS** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**MOT #15** 2021-02-27 08:59**MOT test number** 515947093342**Result** ✓ Passed

- Advice** Both nearside and offside sills corroded
- Advice** Rear brake discs corroded
- Advice** Front brake discs corroded

**MOT #14** 2020-03-07 12:56**MOT test number** 690154604335**Result** ✓ Passed

- Advice** Rear brake discs corroded

**MOT #13** 2019-03-09 13:13**MOT test number** 511481186663**Result** ✓ Passed

- Advice** Rear brake discs corroded

**MOT #12** 2018-03-10 12:37**MOT test number** 107554558437**Result** ✓ Passed**MOT #11** 2017-03-04 12:37**MOT test number** 119063166199**Result** ✓ Passed**Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Front brake discs corroded**MOT #10** 2016-03-23 10:48**MOT test number** 623591868408**Result** ✓ Passed**MOT #9** 2014-11-05 14:22**MOT test number** 105989604334**Result** ✓ Passed**Notice** Both centre inner sill bottoms showing signs of corrosion**Notice** Slight oil leak**MOT #8** 2013-11-06 13:37**MOT test number** 349190013358**Result** ✓ Passed**Notice** Slight play in o/s/f bottom ball joint**Notice** Corrosion on rear back box**Notice** Oil leak

**MOT #7** 2012-11-01 11:29**MOT test number** 399156902330**Result** ✓ Passed**MOT #6** 2012-10-30 13:51**MOT test number** 949534502371**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #5** 2011-11-04 13:45**MOT test number** 628348701324**Result** ✓ Passed**MOT #4** 2010-11-02 14:37**MOT test number** 483456000457**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #3** 2009-11-06 15:15**MOT test number** 423910119358**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2008-11-19 10:22
MOT test number	740684728389
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2008-11-19 09:26
MOT test number	363394428394
Result	✗ Failed
Fail	Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
7 January 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	7 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-11-29
Last registration	2024-01-08
Complete history	<a href="#">See info</a>



Registration #1	2005-11-29	9 mi
Registration #2	2008-11-19	30.738 mi
Registration #3	2008-11-19	30.738 mi
Registration #4	2009-11-06	37.436 mi
Registration #5	2010-11-02	42.787 mi
Registration #6	2011-11-04	45.440 mi
Registration #7	2012-10-30	47.149 mi
Registration #8	2012-11-01	47.149 mi
Registration #9	2013-11-06	49.331 mi
Registration #10	2014-11-05	51.360 mi
Registration #11	2016-03-23	53.015 mi
Registration #12	2016-03-23	53.015 mi
Registration #13	2016-03-23	53.015 mi
Registration #14	2016-03-23	53.015 mi
Registration #15	2016-03-23	53.015 mi
Registration #16	2016-03-23	53.015 mi
Registration #17	2016-03-23	53.015 mi
Registration #18	2016-03-23	53.015 mi
Registration #19	2016-03-23	53.015 mi
Registration #20	2016-03-23	53.015 mi
Registration #21	2016-03-23	53.015 mi
Registration #22	2016-03-23	53.015 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1494 mm
Length	4763 mm
Wheel base	2725 mm
Kerb weight	1567 kg
Max. allowed weight	2127 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JB370021716