





report date: 2024-03-29

General information

Make	BMW
Model	116 116D SPORT
Colour	White
Year of manufacture	2017
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 cc
Cylinders	3
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	80.7 mpg
Consumption combined	72.4 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date	2021-12-14

Pictures 0

Listing price <u>View report</u>

source: cargurus.co.uk

Entry 1

Date	2021-12-13
Pictures	17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-06-25
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	5
Total items failed	5

MOT #6	2023-06-26 13:16
MOT test number	821647452443
Result	✓ Passed
Next expiry date	2024-06-25

MOT #	5	2023-06-26 09:21
MOT te	st number	126628966666
Result		× Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Front Windscreen washer not working (3.5 (a))	

MOT #4		2022-06-14 16:26
MOT test numb	er	918829855283
Result		✓ Passed
Advice Near	rside Rear Tyre worn close to legal limit/worn on edge ty	yre getting low on tread (5.2.3 (e))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2021-09-07 11:35

MOT test number 206557557781

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #2 2021-09-07 10:04

MOT test number 319449236254

Result X Failed

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure outer sidewall (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #1 2020-08-25 15:35

MOT test number 228519442548

Result

Passed

Advice Items removed from driver's view prior to test

Advice Covers and trays fitted blocking view of testable items

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e mier metery	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	
manage of the same	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-04
Last registration	2023-06-26
Complete history	See info



Registration #1	2017-09-04	18 mi
Registration #2	2020-08-25	25.445 mi
Registration #3	2021-09-07	32.924 mi
Registration #4	2021-09-07	32.927 mi
Registration #5		9.777 es
Registration #6		11.777 es
Registration #7		9.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
50295	
50482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4329 mm
Wheel base	2690 mm
Kerb weight	1320 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11

Number of axles 2

Engine number 36919789