



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | VOLVO          |
| Model               | V50 SE S40     |
| Colour              | Blue           |
| Year of manufacture | 2007           |
| Top speed           | 124 mph        |
| 0 - 60 mph          | 10.3 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 123 BHP             |
| Max. torque             | 165 Nm at 4.000 rpm |
| Engine capacity         | 1.798 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 28.8 mpg            |
| Consumption extra urban | 49.6 mpg            |
| Consumption combined    | 39.2 mpg            |
| CO2 emission            | 174 g/km            |
| CO2 label               | H                   |





## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2021-10-22 |
| MOT pass rate      | 73 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 4          |
| Total advice items | 13         |
| Total items failed | 4          |

|                  |                  |
|------------------|------------------|
| MOT #15          | 2020-09-23 13:06 |
| MOT test number  | 108101697508     |
| Result           | ✓ Passed         |
| Next expiry date | 2021-10-22       |

|   |                  |
|---|------------------|
| MOT #14   | 2020-09-23 08:13 |
| MOT test number   | 966052844039     |
| Result  | ✗ Failed         |
| <b>MAJOR</b> Nearside Rear Position lamp not working (4.2.1 (a) (ii)) |                  |

|                 |                  |
|-----------------|------------------|
| MOT #13         | 2019-10-16 08:30 |
| MOT test number | 994936186595     |
| Result          | ✓ Passed         |

|   |                  |
|---|------------------|
| MOT #12   | 2018-10-16 12:00 |
| MOT test number   | 228051069720     |
| Result  | ✓ Passed         |
| <b>Advice</b> Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) |                  |
| <b>Advice</b> Offside rear tyre worn on inside edge   |                  |

**MOT #11** 2018-10-15 12:42**MOT test number** 999626613267**Result** ✗ Failed**Advice** Offside rear tyre worn on inside edge**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2017-10-17 08:46**MOT test number** 574467425679**Result** ✓ Passed**MOT #9** 2017-10-17 08:46**MOT test number** 324805779021**Result** ✗ Failed**Pass with rectification** Offside Rear position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #8** 2016-10-19 08:40**MOT test number** 568537267199**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured both sides (1.4.A.2f)**MOT #7** 2015-10-21 10:27**MOT test number** 125507939351**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-10-23 10:34**MOT test number** 546226494244**Result** ✓ Passed**MOT #5** 2014-10-21 09:28**MOT test number** 358614094253**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2013-10-23 12:16**MOT test number** 437056093225**Result** ✓ Passed**MOT #3** 2012-10-15 17:12**MOT test number** 658389382213**Result** ✓ Passed**MOT #2** 2011-09-19 16:47**MOT test number** 457152661209**Result** ✓ Passed**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Notice** Osr door will not open**MOT #1** 2010-10-01 11:19**MOT test number** 393904870267**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕  
Untaxed

Tax expired:  
18 December 2020

✕  
MOT

Expired:  
22 October 2021

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 18 December 2020     |
| Days left        | 1227 days too late              |
| MOT expiry date  | 22 October 2021                 |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | H          |
| Single payment (12 months)              | £ 290,00,- |
| Single six month payment                | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-09-28 |
| Current registration | *****      |
| Plate since          | 2019-09-28 |

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 16                       |
| First mileage registration | 2007-09-28               |
| Last registration          | 2020-09-23               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2007-09-28 | 7 mi       |
| Registration #2  | 2010-10-01 | 29.313 mi  |
| Registration #3  | 2011-09-19 | 40.816 mi  |
| Registration #4  | 2012-10-15 | 51.741 mi  |
| Registration #5  | 2013-10-23 | 57.220 mi  |
| Registration #6  | 2014-10-21 | 61.579 mi  |
| Registration #7  | 2014-10-23 | 61.613 mi  |
| Registration #8  | 2015-10-21 | 65.941 mi  |
| Registration #9  | 2016-10-21 | 70.269 mi  |
| Registration #10 | 2017-10-21 | 74.597 mi  |
| Registration #11 | 2018-10-21 | 78.925 mi  |
| Registration #12 | 2019-10-21 | 83.253 mi  |
| Registration #13 | 2020-09-23 | 87.581 mi  |
| Registration #14 | 2021-09-23 | 91.909 mi  |
| Registration #15 | 2022-09-23 | 96.237 mi  |
| Registration #16 | 2023-09-23 | 100.565 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1770 mm |
| Height              | 1452 mm |
| Length              | 4468 mm |
| Wheel base          | 2640 mm |
| Kerb weight         | 1376 kg |
| Max. allowed weight | 1850 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 4                     |
| Number of seats    | 5                     |

|                        |        |
|------------------------|--------|
| <b>Number of axles</b> | 2      |
| <b>Engine number</b>   | 103249 |