



YX65VZY

report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO EASY
Colour	Red
Year of manufacture	-
Top speed	100 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	127 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-13
Pictures	11
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #11	2023-10-05 15:37
MOT test number	702743885787
Result	✓ Passed
Next expiry date	2024-10-05
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
Advice	Central Rear Passenger seat(s) missing at time of test
Advice	Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10	2023-10-05 10:18
MOT test number	662869085338
Result	✗ Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Central Rear Passenger seat(s) missing at time of test

**MOT #9** 2022-10-06 15:59**MOT test number** 806931177389**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))**MOT #8** 2022-10-05 08:01**MOT test number** 199081228233**Result** ✗ Failed**Advice** Offside Rear All direction indicators slightly discoloured (4.4.3 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #7** 2021-10-06 12:53**MOT test number** 429716529856**Result** ✓ Passed**MOT #6** 2021-10-05 15:55**MOT test number** 602389872690**Result** ✗ Failed**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #5** 2020-08-13 16:26**MOT test number** 924822395208**Result** ✓ Passed**MOT #4** 2020-08-12 15:47**MOT test number** 806577816046**Result** ✗ Failed**Fail** Offside Front Macpherson strut mounting corroded and seriously weakened (5.3.3 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #3** 2019-08-21 15:19**MOT test number** 148742624417**Result** ✓ Passed**Advice** Offside Brake cable damaged but not to excess mount (1.1.15 (a))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**MOT #2** 2019-08-19 10:08**MOT test number** 660452641088**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Emissions not tested (8.2.1.2 (d))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Offside Brake cable damaged but not to excess mount (1.1.15 (a))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))



MOT #1

2018-08-15 09:29

MOT test number

756752053105

Result

✓ Passed

- Advice

Handbrake lever has insufficient reserve travel
- Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor

Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))
- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Middle exhaust mount rubber spilt/broken



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	YX65VZY
Plate since	2019-09-28
Current registration	YX65VZY
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-10-26
Last registration	2023-10-05
Complete history	See info



Registration #1	2015-10-26	26 mi
Registration #2	2018-08-15	20.514 mi
Registration #3	2019-08-19	26.143 mi
Registration #4	2019-08-21	26.145 mi
Registration #5	2020-08-12	29.547 mi
Registration #6	2020-08-13	29.548 mi
Registration #7	2020-08-20	29.557 mi
Registration #8	2020-08-20	29.557 mi
Registration #9	2020-08-20	29.557 mi
Registration #10	2020-08-20	29.557 mi
Registration #11	2020-08-20	29.557 mi
Registration #12	2020-08-20	29.557 mi
Registration #13	2020-08-20	29.557 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4406 mm
Max. allowed weight	1975 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	4044020