



report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 GLX
Colour	Grey
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-05-12
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	25
Total items failed	18

MOT #19 2023-05-03 14:45

MOT test number 548371783309

Result ✓ Passed

Next expiry date 2024-05-12

**Advice** Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

**Advice** Front Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

MOT #18 2022-05-13 14:06

MOT test number 917508704760

Result ✓ Passed

MOT #17 2021-04-27 12:38

MOT test number 108589408618

Result ✓ Passed

**Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))

**MOT #16** 2019-11-06 14:28**MOT test number** 823381189830**Result** ✓ Passed

- Advice** Offside Front Coil spring worn (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Upper Macpherson strut mounting damaged but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material both sides in arches (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Shock absorbers has slight external damage to the casing both sides corroded (5.3.2 (b))

**MOT #15** 2018-11-09 09:40**MOT test number** 947244828336**Result** ✓ Passed**MOT #14** 2018-11-08 17:00**MOT test number** 391708286389**Result** ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #13** 2017-11-16 17:18**MOT test number** 617879677633**Result** ✓ Passed

- Advice** Front Front suspension has slight movement at a wishbone pin or bush both sides (2.5.A.1c)

**MOT #12** 2016-12-29 15:20**MOT test number** 448736655079**Result** ✓ Passed**MOT #11** 2016-12-29 14:22**MOT test number** 754991414396**Result** ✗ Failed**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #10** 2015-12-05 11:28**MOT test number** 471633614308**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-12-06 12:35**MOT test number** 457360444375**Result** ✓ Passed**MOT #8** 2013-12-20 12:39**MOT test number** 918834353361**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #7**

2013-12-20 10:37

**MOT test number**

597424253368

**Result****✗ Failed****Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside Headlamp aim too low (1.8)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Rear registration plate insecure (6.3.1b)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #6**

2013-01-03 16:04

**MOT test number**

616083703097

**Result****✓ Passed****Notice** Exhaust mounts to front and rear corroding

**MOT #5** 2012-12-29 12:59**MOT test number** 528414262354**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Notice** Exhaust mounts to front and rear corroding**Fail** Offside Front Bonded suspension unit bonding failed and part of unit is likely to become displaced (2.4.F.2)**Fail** Offside Front coil spring fractured (2.4.C.1a)**Fail** Offside Headlamp aim too low (1.8)**Fail** Nearside Front coil spring fractured (2.4.C.1a)**MOT #4** 2011-12-27 13:36**MOT test number** 855481561304**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2010-12-16 14:19**MOT test number** 170210950304**Result** ✓ Passed**Notice** Front brake discs lipped**MOT #2** 2009-12-11 12:22**MOT test number** 310635749356**Result** ✓ Passed



MOT #1	2009-12-11 12:11
MOT test number	233575249332
Result	✗ Failed
Fail	Offside Headlamp aim too low (1.8)
Fail	Nearside Headlamp aim too low (1.8)
Notice	Child seat fitted not allowing full inspection of adult belt





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
12 May 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	12 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-12-21
Last registration	2023-05-03
Complete history	<a href="#">See info</a>



Registration #1	2006-12-21	27 mi
Registration #2	2009-12-11	21.227 mi
Registration #3	2009-12-11	21.227 mi
Registration #4	2010-12-16	27.354 mi
Registration #5	2011-12-27	34.782 mi
Registration #6	2012-12-29	42.523 mi
Registration #7	2013-01-03	42.525 mi
Registration #8	2013-12-20	50.491 mi
Registration #9	2013-12-20	50.491 mi
Registration #10	2014-12-06	58.502 mi
Registration #11	2015-05-20	59.557 mi
Registration #12	2015-05-20	59.557 mi
Registration #13	2015-05-20	59.557 mi
Registration #14	2015-05-20	59.557 mi
Registration #15	2015-05-20	59.557 mi
Registration #16	2015-05-20	59.557 mi
Registration #17	2015-05-20	59.557 mi
Registration #18	2015-05-20	59.557 mi
Registration #19	2015-05-20	59.557 mi
Registration #20	2015-05-20	59.557 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1605 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1205 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1187530