



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	VITO 111 CDI COMPACT P/V
Colour	Blue
Year of manufacture	2005
Gearbox	5 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

**Entry 1**

Date	2021-07-29
Pictures	11
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

<b>MOT expiry date</b>	2023-06-29
<b>MOT pass rate</b>	75 %
<b>MOT passed</b>	15
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	104
<b>Total items failed</b>	7

<b>MOT #20</b>	2022-06-18 12:14
<b>MOT test number</b>	192913674488
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-06-29
<b>Advice</b>	Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #19</b>	2021-06-30 10:55
<b>MOT test number</b>	516693309767
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Offside Front Suspension component mounting prescribed area is corroded but not considered excessive jacking pad (5.3.6 (a) (i))
<b>Advice</b>	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive jacking pad (5.3.6 (a) (i))



MOT #18

2021-06-17 09:23

MOT test number

681445199339

Result

✗ Failed

**MAJOR** Nearside Front Brake hose excessively damaged (1.1.12 (b) (ii))

**MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner and outer (5.3.6 (a) (i))

**Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive jacking pad (5.3.6 (a) (i))

**DANGEROUS** Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MAJOR** Offside Front Headlamp lens seriously defective no pattern (4.1.1 (b) (ii))

**MAJOR** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MAJOR** Offside Front Brake hose excessively damaged (1.1.12 (b) (ii))

**MAJOR** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner and outer (5.3.6 (a) (i))

**MAJOR** Nearside Front Headlamp lens seriously defective no pattern (4.1.1 (b) (ii))

**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive jacking pad (5.3.6 (a) (i))

**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

**MAJOR** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))



**MOT #17** 2020-06-05 10:56

**MOT test number** 427736489495

**Result** ✔ Passed

- Advice** Direction indicator slightly discoloured both front and both rear (4.4.3 (a))
- Advice** Offside Front steering rack gaiter slightly twisted
- Advice** Brake hose slightly deteriorated all four (1.1.12 (b) (ii))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Corrosion on both seals on rear suspension prescribed areas - not deemed as excessive at time of test
- Advice** Registration plate deteriorated but not likely to be misread both (0.1 (b))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))



MOT #16

2019-05-17 14:58

MOT test number

626846957667

Result

✓ Passed

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Centre seat belt slow to retract
- Advice** Offside Rear Outer wheel arch corroded
- Advice** Nearside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Offside Rear Nail in tyre
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive jacking point (5.3.6 (a) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive suspension arm mounting area (5.3.6 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front seat belt slow to retract
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive jacking point (5.3.6 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive suspension arm mounting area (5.3.6 (a) (i))
- Advice** Nearside Front Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))



<b>MOT #15</b>	2019-05-17 09:33
<b>MOT test number</b>	725079660224
<b>Result</b>	✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive suspension arm mounting area (5.3.6 (a) (i))

**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Front Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

**MAJOR** Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

**MAJOR** Nearside Front Headlamp aim not tested (4.1.2 (b))

**Advice** Offside Rear Outer wheel arch corroded

**Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive jacking point (5.3.6 (a) (i))

**MAJOR** Offside Front Brake prescribed area is excessively corroded chassis area at A.B.S PUMP (1.1.21 (e) (i))

**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**Advice** Centre seat belt slow to retract

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive suspension arm mounting area (5.3.6 (a) (i))

**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Front wiper smears slightly

**Advice** Nearside Front Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Nearside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Offside Front seat belt slow to retract

**Advice** Offside Rear Nail in tyre

**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive jacking point (5.3.6 (a) (i))

**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Advice** Nearside Front wiper smears slightly



MOT #14 2018-05-24 10:01

MOT test number 485424345926

Result ✔ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Front Brake hose slightly damaged (1.1.12 (b) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Body and sills corroded, however not within prescribed areas or excessive
- Minor** Offside Front Brake hose slightly damaged (1.1.12 (b) (i))

MOT #13 2017-05-19 09:17

MOT test number 825906516716

Result ✔ Passed

- Advice** Both Outer Sills Corroded But Not Dangerous
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Rear Door Jam/Inner Wing Excessively Corroded But Not Dangerous
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Outer Sill (2.4.A.3)



MOT #12 2017-05-18 10:07

MOT test number 598654617832

Result ✗ Failed

- Advice** Both Outer Sills Corroded But Not Dangerous
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Outer Sill (2.4.A.3)
- Advice** Offside Rear Door Jam/Inner Wing Excessively Corroded But Not Dangerous
- Fail** Offside Front Inner Seat belt anchorage prescribed area is excessively corroded Outrigger (5.2.6)
- Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded Inner Sill (2.4.A.3)
- Fail** Nearside Front Inner Seat belt anchorage prescribed area is excessively corroded Outrigger (5.2.6)

MOT #11 2016-05-17 08:07

MOT test number 463947956672

Result ✓ Passed

- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)



**MOT #10** 2015-05-20 08:54

**MOT test number** 187300945148

**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Front jacking points corroded

**MOT #9** 2014-04-08 12:15

**MOT test number** 185158494403

**Result** ✓ Passed

- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

**MOT #8** 2013-04-10 16:21

**MOT test number** 159020903113

**Result** ✓ Passed

**MOT #7** 2012-03-20 09:33

**MOT test number** 326800282012

**Result** ✓ Passed

- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



<b>MOT #6</b>	2012-03-20 09:33
<b>MOT test number</b>	915820782011
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
<b>Pass with rectification</b>	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
<b>Advice</b>	Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

<b>MOT #5</b>	2011-04-06 10:56
<b>MOT test number</b>	657906491096
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2010-04-13 09:17
<b>MOT test number</b>	334393100141
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2009-03-23 10:33
<b>MOT test number</b>	473572089045
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2008-03-11 11:07
<b>MOT test number</b>	344711678072
<b>Result</b>	✓ Passed
<b>Notice</b>	Front wipers smear slightly.
<b>Notice</b>	Both front tyres worn below the limit on the edges.



**MOT #1** 2008-03-11 11:07

**MOT test number** 333991278049

**Result** ✗ Failed

**Notice** Both front tyres worn below the limit on the edges.

**Pass with rectification** Offside Headlamp aim too high (1.8)

**Notice** Front wipers smear slightly.

**Pass with rectification** Nearside Headlamp aim too high (1.8)



Tax & MOT check

**×**  
**Untaxed**  
Tax expired:  
26 March 2024

**×**  
**MOT**  
Expired:  
29 June 2023

**Tax status** Expired at 26 March 2024

**Days left** 34 days too late

**MOT expiry date** 29 June 2023

**Full MOT history** [See MOT history](#)




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<b>RE050FK</b>
Plate since	2019-03-29
Current registration	<b>RE050FK</b>
Plate since	2019-03-29

More info >



**Finance check**

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-03-16
Last registration	2022-06-18
Complete history	<a href="#">See info</a>



Registration #1	2005-03-16	20 mi
Registration #2	2008-03-11	33.512 mi
Registration #3	2009-03-23	42.368 mi
Registration #4	2010-04-13	50.947 mi
Registration #5	2011-04-06	59.141 mi
Registration #6	2012-03-20	64.999 mi
Registration #7	2013-04-10	70.987 mi
Registration #8	2014-04-08	77.910 mi
Registration #9	2015-05-20	84.284 mi
Registration #10	2016-05-17	90.300 mi
Registration #11	2017-05-20	95.317 mi
Registration #12	2018-05-20	100.334 mi
Registration #13	2019-05-20	105.351 mi
Registration #14	2020-05-20	110.368 mi
Registration #15	2021-05-20	115.385 mi
Registration #16	2022-05-20	120.402 mi
Registration #17	2023-05-20	125.419 mi
Registration #18	2024-05-20	130.436 mi
Registration #19	2025-05-20	135.453 mi
Registration #20	2026-05-20	140.470 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	64698250107897