



General information

Make	MINI
Model	MINI COOPER S
Colour	Grey
Year of manufacture	2011
Top speed	137 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	55.4 mpg
Consumption combined	42.8 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2025-03-26
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	11
Total items failed	5

MOT #12	2024-03-27 15:19
MOT test number	797214669706
Result	✓ Passed
Next expiry date	2025-03-26
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11	2023-03-03 11:15
MOT test number	489590344680
Result	✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10	2023-03-02 10:25
MOT test number	285925682203
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #9** 2022-03-16 15:41**MOT test number** 737915180522**Result** ✓ Passed**MOT #8** 2021-03-05 09:47**MOT test number** 595889427344**Result** ✓ Passed**MOT #7** 2020-03-18 16:46**MOT test number** 856606145320**Result** ✓ Passed**MOT #6** 2019-11-06 08:16**MOT test number** 416930832741**Result** ✗ Failed**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #5** 2018-10-03 10:28**MOT test number** 306415383568**Result** ✓ Passed**MOT #4** 2017-08-07 14:57**MOT test number** 355399949543**Result** ✓ Passed



MOT #3	2016-04-01 11:27
MOT test number	170445382554
Result	✓ Passed
Advice	Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
Advice	Both front wishbones rear bushes slight movement.
Advice	Nearside Front Tyre worn close to the legal limit on limit inner and outer edge (4.1.E.1)
Advice	Offside front tyre lightly wearing on edge's,n/s rear lightly stepping on inner edge.

MOT #2	2015-04-02 14:42
MOT test number	789102195013
Result	✓ Passed
MOT #1	2014-04-05 12:43
MOT test number	786845294010
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
26 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	26 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-01
Last registration	2024-03-27
Complete history	<a href="#">See info</a>



Registration #1	2011-03-01	29 mi
Registration #2	2014-04-05	10.443 mi
Registration #3	2015-04-02	14.289 mi
Registration #4	2016-04-01	21.736 mi
Registration #5	2017-08-07	33.092 mi
Registration #6	2018-10-03	45.340 mi
Registration #7	2019-11-06	53.462 mi
Registration #8	2020-05-20	55.277 mi
Registration #9	2020-05-20	55.277 mi
Registration #10	2020-05-20	55.277 mi
Registration #11	2020-05-20	55.277 mi
Registration #12	2020-05-20	55.277 mi
Registration #13	2020-05-20	55.277 mi
Registration #14	2020-05-20	55.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1255 kg
Max. allowed weight	1685 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number	C008I902
---------------	----------