





report date: 2024-03-28

#### General information

Make	FIAT
Model	500C S
Colour	Blue
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 2

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk


Entry 1

Date	2021-06-05
Pictures	68

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



AX14HVM report date: 2024-03-28

MOT history

MOT expiry date	2024-09-20
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	6

MOT #10		2023-09-21 10:46
MOT test	number	323421795893
Result		✓ Passed
Next expi	ry date	2024-09-20
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT** #9 2023-09-19 09:47 325288558929 **MOT** test number Result × Failed Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) **Advice** Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c)) Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) Advice Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c)) Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #8	2022-08-23 11:32
MOT test number	431804187660
Result	<b>✓</b> Passed
MOT #7	2021-07-29 12:52
MOT test number	510327349655
Result	<b>✓</b> Passed
Advice Rear exhaust clamp corroded	

MOT #6	2021-07-27 11:17
MOT test number	156091044417
Result	<b>×</b> Failed
Advice Rear exhaust clamp corroded	
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5	2020-07-03 13:11
MOT test number	540041249737
Result	<b>✓</b> Passed
MOT #4	2019-07-24 12:09
MOT test number	373962188360
Result	✓ Passed
Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #3	2018-07-24 14:03
MOT test number	916881958980
Result	✓ Passed
MOT #2	2018-07-23 15:03
MOT test number	920448565698
Result	<b>X</b> Failed
Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #1	2017-07-06 13:53
MOT test number	515593133221
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	20 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	biotom
UWNEI	nision
OWNICI	1113601 )

*		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I		e?
***************************************		
***************************************		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		0.00.0
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-07-24
Last registration	2023-09-21
Complete history	See info



Registration #1	2014-07-24	25 mi
Registration #2	2017-07-06	19.002 mi
Registration #3	2018-07-23	24.824 mi
Registration #4	2018-07-24	24.824 mi
Registration #5	2019-07-24	30.267 mi
Registration #6	2020-07-03	35.063 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number 0709926