



HYUNDAI



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | HYUNDAI |
| Model | GETZ CDX |
| Colour | Silver |
| Year of manufacture | - |
| Top speed | 106 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 96 BHP |
| Max. torque | 126 Nm at 3.200 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 47.1 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-14 |
| Pictures | 22 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|-------------------------|---|
| MOT #23 | 2021-09-30 16:36 |
| MOT test number | 831226615909 |
| Result | ✓ Passed |
| Next expiry date | 2022-09-29 |
| Advice | Play in nearside front top mount |
| Advice | Front lower ball joint gaiters deteriorated |

| | |
|------------------------|--|
| MOT #22 | 2021-09-29 16:34 |
| MOT test number | 347493832863 |
| Result | ✗ Failed |
| Advice | Play in nearside front top mount |
| Fail | Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt NEARSIDE FRONT (5.3.4 (b) (ii)) |
| Advice | Front lower ball joint gaiters deteriorated |

| | |
|------------------------|------------------|
| MOT #21 | 2021-01-22 15:39 |
| MOT test number | 555967366361 |
| Result | ✓ Passed |

| | |
|------------------------|---|
| MOT #20 | 2021-01-22 10:35 |
| MOT test number | 115220095988 |
| Result | ✗ Failed |
| Fail | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Fail | Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) |
| Fail | Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) |

| | |
|------------------------|------------------|
| MOT #19 | 2020-01-29 15:16 |
| MOT test number | 754186662687 |
| Result | ✓ Passed |

**MOT #18** 2020-01-29 10:40**MOT test number** 165014859315**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #17** 2019-02-06 17:22**MOT test number** 535692367576**Result** ✓ Passed**MOT #16** 2019-02-06 16:14**MOT test number** 731498433129**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**MOT #15** 2018-01-19 14:05**MOT test number** 764684524851**Result** ✓ Passed**MOT #14** 2018-01-16 15:03**MOT test number** 195069274465**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #13** 2017-01-13 16:56**MOT test number** 279923236876**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2017-01-13 12:59**MOT test number** 122017925184**Result** ✗ Failed**Fail** Offside front brake binding (3.7.B.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #11** 2016-01-15 16:04**MOT test number** 782641238432**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2016-01-12 15:07**MOT test number** 855327441526**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside front brake binding (3.7.B.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2015-01-08 12:29**MOT test number** 408838705090**Result** ✓ Passed

- Notice** Childs seat fitted nearside rear unable to fully examine seat belt
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #8 2014-01-27 14:38**MOT test number** 539507624052**Result** ✓ Passed**MOT #7** 2013-01-24 12:53**MOT test number** 946804023071**Result** ✓ Passed

- Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Notice** N/s/r and o/s/r back plates slightly corroded
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #6 2011-11-16 13:58**MOT test number** 819180121391**Result** ✓ Passed

**MOT #5** 2011-11-16 13:58**MOT test number** 268320821314**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #4** 2010-11-01 12:41**MOT test number** 181705300340**Result** ✓ Passed**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-11-01 12:41**MOT test number** 544685800341**Result** ✗ Failed**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #2** 2009-10-16 15:36**MOT test number** 434049389200**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #1 | 2008-10-22 09:47 |
| MOT test number | 850756198278 |
| Result | ✓ Passed |
| Notice | Offside front tyre wearing inside edge |
| Notice | Nearside front tyre wearing outside edge |
| Notice | Rear wiper blade ends split |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 23 |
| First mileage registration | 2005-11-14 |
| Last registration | 2021-09-30 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2005-11-14 | 20 mi |
| Registration #2 | 2008-10-22 | 25.960 mi |
| Registration #3 | 2009-10-16 | 33.324 mi |
| Registration #4 | 2010-11-01 | 41.040 mi |
| Registration #5 | 2011-11-16 | 44.529 mi |
| Registration #6 | 2013-01-24 | 44.680 mi |
| Registration #7 | 2014-01-27 | 48.564 mi |
| Registration #8 | 2015-01-08 | 53.280 mi |
| Registration #9 | 2016-01-12 | 55.954 mi |
| Registration #10 | 2016-01-15 | 55.954 mi |
| Registration #11 | 2017-01-13 | 62.554 mi |
| Registration #12 | 2017-01-13 | 62.554 mi |
| Registration #13 | 2018-01-01 | 65.000 mi |
| Registration #14 | 2018-01-01 | 65.000 mi |
| Registration #15 | 2018-01-01 | 65.000 mi |
| Registration #16 | 2018-01-01 | 65.000 mi |
| Registration #17 | 2018-01-01 | 65.000 mi |
| Registration #18 | 2018-01-01 | 65.000 mi |
| Registration #19 | 2018-01-01 | 65.000 mi |
| Registration #20 | 2018-01-01 | 65.000 mi |
| Registration #21 | 2018-01-01 | 65.000 mi |
| Registration #22 | 2018-01-01 | 65.000 mi |
| Registration #23 | 2018-01-01 | 65.000 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1665 mm |
| Height | 1490 mm |
| Length | 3825 mm |
| Wheel base | 2455 mm |
| Kerb weight | 1025 kg |
| Max. allowed weight | 1510 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|-------------|
| Number of axles | 2 |
| Engine number | G4EE5242551 |