






### General information

Make	FIAT
Model	500C TWINAIR LOUNGE
Colour	Green
Year of manufacture	2015
Top speed	107 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	60.1 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	92 g/km
CO2 label	А





AP64CPF report date: 2024-03-29

Internet history		
Entry 3		
Date	2021-10-25	
Pictures	5	
Listing price	View report	
AWAITING DREPARATION	VIDEOS	finance to fit your mstances. Derby train station
Entry 2		
Date	2021-10-23	
Pictures	5	
Listing price	View report	
PERSONALISED   Available by   request   Brit Matternal   With Matternal   Brit Matternal   Source: autotrader.co.uk	10 minute walk from	finance to fit your mstances.
Entry 1		
Date	2021-01-21	
Pictures	19	

Listing price

19 <u>View report</u>



source: yesauto.com



### MOT history

MOT expiry date	2024-12-21
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #9		2023-12-11 13:09
<b>MOT test number</b> 6845931861		684593186161
Result		✓ Passed
Next expi	ry date	2024-12-21
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))

MOT #8 2022-12-07 13:49 **MOT test number** 989728077357 Result 🗸 Passed Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))





MOT #7	2	022-12-07 09:34
MOT test	number	395910734186
Result		🗙 Failed
<b>Fail</b> N	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure	(5.2.3 (d) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	.4 (a) (ii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

МОТ #6	2021-12-03 09:50
MOT test number	335907441327
Result	✓ Passed
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #5	2020-12-22 15:11
MOT test number	323055315728
Result	✓ Passed

MOT #4	2020-01-27 14:41
MOT test number	480728106565
Result	✓ Passed

MOT #3	2019-01-25 16:12
MOT test number	790567615851
Result	✓ Passed
Advice Front brake discs slightly corroded	





MOT #2	2018-01-18 15:45
MOT test number	611482137272
Result	✓ Passed
MOT #1	2018-01-18 15:45
MOT test number	447584649803
Result	× Failed
Pass with rectification	Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)



Tax & MOT check

<b>Tax due:</b> 1 February 2025	✓ Taxed	<b>Expires:</b> 21 December 2024	мот
Tax status			Valid until 1 February
Days left			278
MOT expiry date			21 December 2024
Full MOT history			See MOT history
Tax calculation		18	

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
************	
********	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-01-29
Last registration	2023-12-11
Complete history	See info



Registration #1	2015-01-29	13 mi
Registration #2	2018-01-18	23.671 mi
Registration #3	2018-01-18	23.671 mi
Registration #4	2019-01-25	37.364 mi
Registration #5	2020-01-27	47.498 mi
Registration #6	2020-12-22	55.536 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.117 esi





### Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	0289198