



LFI40JR


report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Silver
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A






Internet history

Entry 3



Date	2021-06-26
Pictures	34
Listing price	View report



source: [heycar.co.uk](#)

Entry 2

Date	2021-06-06
Pictures	33
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2021-05-24
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-14
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	22
Total items failed	5

MOT #12	2023-11-15 09:49
MOT test number	426519405949
Result	✓ Passed
Next expiry date	2024-11-14

MOT #11	2023-11-14 10:58
MOT test number	642783099646
Result	✗ Failed
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #10	2023-03-10 15:33
MOT test number	974588216442
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Exhaust mounting defective front and rear (6.1.2 (a))
Advice	Tyre worn close to legal limit/worn on edge both front wearing on edges (5.2.3 (e))

**MOT #9**

2022-03-07 11:26

MOT test number

175644817506

Result

✓ Passed

Advice Sills floor chassi brake pipes brake hoses all springs sup rubbers all req clean wax oil grease now through out PREVENTIVE MAINTANACE DOES WORK DO NOW WHILE GOOD

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened INNER REAR DISCS SCORED WORN UNEVEN WEAR ON PADS STRIP SERVICE REAR BRAKES SOON STRONG ADVISE (1.1.14 (a) (ii))

MOT #8

2022-03-07 11:26

MOT test number

617742566707

Result

✗ Failed

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened INNER REAR DISCS SCORED WORN UNEVEN WEAR ON PADS STRIP SERVICE REAR BRAKES SOON STRONG ADVISE (1.1.14 (a) (ii))

Advice Sills floor chassi brake pipes brake hoses all springs sup rubbers all req clean wax oil grease now through out PREVENTIVE MAINTANACE DOES WORK DO NOW WHILE GOOD

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #7

2021-03-01 10:13

MOT test number

638160452582

Result

✓ Passed

Advice Offside Front Macpherson strut mounting damaged but not seriously weakened TOP MOUNT (5.3.3 (b) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement TOP MOUNT (5.3.4 (a) (i))

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2021-03-01 10:13**MOT test number** 659167418904**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Front Macpherson strut mounting damaged but not seriously weakened TOP MOUNT (5.3.3 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement TOP MOUNT (5.3.4 (a) (i))**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2020-03-14 09:03**MOT test number** 921588453162**Result** ✓ Passed**MOT #4** 2020-03-14 09:02**MOT test number** 869170439603**Result** ✗ Failed**Pass with rectification** Offside Rear Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #3** 2019-03-07 09:39**MOT test number** 594952609991**Result** ✓ Passed**Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Items removed from driver's view prior to test sticker relocated**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #2	2018-02-19 09:00
MOT test number	681550097830
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2017-03-13 13:00
MOT test number	302527186251
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
14 November 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	14 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-03-15
Last registration	2023-11-15
Complete history	See info



Registration #1	2014-03-15	27 mi
Registration #2	2017-03-13	32.814 mi
Registration #3	2018-02-19	40.989 mi
Registration #4	2019-03-07	48.512 mi
Registration #5	2020-03-14	53.671 mi
Registration #6	2020-03-14	53.671 mi
Registration #7	2021-03-01	55.208 mi
Registration #8	2021-03-01	55.208 mi
Registration #9	2022-03-01	55.208 mi
Registration #10	2022-03-01	55.208 mi
Registration #11	2022-03-01	55.208 mi
Registration #12	2022-03-01	55.208 mi
Registration #13	2022-03-01	55.208 mi
Registration #14	2022-03-01	55.208 mi
Registration #15	2022-03-01	55.208 mi
Registration #16	2022-03-01	55.208 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3167254