



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Blue
Year of manufacture	2007
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J







Internet history

Entry 1

Date	2021-11-01
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-21
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	30
Total items failed	9

MOT #18	2023-06-22 08:23
MOT test number	789428216108
Result	✓ Passed
Next expiry date	2024-06-21
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #17	2022-04-01 08:36
MOT test number	741699977296
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16** 2022-03-31 08:24**MOT test number** 859001729096**Result** ✗ Failed**Fail** Offside Headlamp light source and lamp not compatible (4.1.4 (c))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Headlamp light intensity severely reduced (4.1.4 (a))**Fail** Nearside Headlamp light source and lamp not compatible (4.1.4 (c))**Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))**MOT #15** 2021-01-09 11:34**MOT test number** 832255662557**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2021-01-09 10:39**MOT test number** 364606430235**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-01-09 17:25**MOT test number** 968689362863**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Rear Brake pad(s) wearing thin both rear pads getting low (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2019-01-04 16:51**MOT test number** 620105794088**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-01-10 10:22**MOT test number** 988866484490**Result** ✓ Passed**MOT #10** 2017-01-11 11:00**MOT test number** 374219829573**Result** ✓ Passed**Advice** Nearside Front Outer Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2017-01-10 15:46**MOT test number** 357104251969**Result** ✗ Failed**Advice** Nearside Front Outer Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2015-12-21 13:24**MOT test number** 466650730250**Result** ✓ Passed**Advice** Brake pad(s) wearing thin Nearside and offside front (3.5.1g)**Advice** Offside Tyre worn close to the legal limit Rear (4.1.E.1)**Advice** Nearside Tyre worn close to the legal limit Rear (4.1.E.1)**MOT #7** 2014-12-23 11:05**MOT test number** 375997354363**Result** ✓ Passed**Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #6** 2014-12-23 11:05**MOT test number** 327197454390**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #5** 2013-12-28 15:42**MOT test number** 349612663303**Result** ✓ Passed**Notice** NEAR SIDE REAR TYRE HAS CRACKS ON INNER AND OUTER WALLS**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** OFFSIDE REAR TYRE HAS CRACKS ON OUTER WALL**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-12-28 11:52**MOT test number** 656833162354**Result** ✓ Passed**MOT #3** 2012-05-22 14:46**MOT test number** 386333242138**Result** ✓ Passed**MOT #2** 2011-05-27 08:57**MOT test number** 277597641404**Result** ✓ Passed**MOT #1** 2010-11-04 12:58**MOT test number** 784468300329**Result** ✓ Passed**Notice** Both front tyre treads slight wear on edges



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
21 June 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-29
Current registration	XXXX XX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-30
Last registration	2023-06-22
Complete history	See info



Registration #1	2007-11-30	21 mi
Registration #2	2010-11-04	14.362 mi
Registration #3	2011-05-27	15.792 mi
Registration #4	2012-05-22	22.335 mi
Registration #5	2012-12-28	25.913 mi
Registration #6	2013-12-28	30.200 mi
Registration #7	2014-12-23	33.243 mi
Registration #8	2015-12-21	34.707 mi
Registration #9	2017-01-10	37.890 mi
Registration #10	2017-01-11	37.895 mi
Registration #11	2019-05-22	39.337 mi
Registration #12	2019-05-22	39.337 mi
Registration #13	2019-05-22	39.337 mi
Registration #14	2019-05-22	39.337 mi
Registration #15	2019-05-22	39.337 mi
Registration #16	2019-05-22	39.337 mi
Registration #17	2019-05-22	39.337 mi
Registration #18	2019-05-22	39.337 mi
Registration #19	2019-05-22	39.337 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1312 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC6749744