



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Black
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.2 mpg
Consumption combined	32.1 mpg
CO2 emission	221 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-13
Pictures	2
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-04-25
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	17
Total items failed	3

MOT #19 2024-04-25 09:35

MOT test number 236686630750

Result ✓ Passed

Next expiry date 2025-04-25

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Offside Front Suspension arm ball joint has slight play \*marked\* (5.3.4 (a) (i))

MOT #18 2023-04-26 11:00

MOT test number 963796639181

Result ✓ Passed

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Corroded and lipped (1.1.14 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Lipped and corroded (1.1.14 (a) (ii))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Nail in tyre

**MOT #17** 2023-04-14 11:52**MOT test number** 416437846410**Result** ✗ Failed**Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))**Advice** Offside Front Nail in tyre**MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MAJOR** Nearside Front Headlamp insecure (4.1.1 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2022-04-13 10:48**MOT test number** 757508798031**Result** ✓ Passed**MOT #15** 2021-04-20 07:11**MOT test number** 487951844606**Result** ✓ Passed**MOT #14** 2020-04-23 07:17**MOT test number** 533005251860**Result** ✓ Passed**MOT #13** 2019-04-16 07:25**MOT test number** 763590690186**Result** ✓ Passed



<b>MOT #12</b>	2018-04-17 07:14
<b>MOT test number</b>	847424869741
<b>Result</b>	✓ Passed
<b>MOT #11</b>	2017-04-18 07:17
<b>MOT test number</b>	661295801972
<b>Result</b>	✓ Passed
<b>MOT #10</b>	2016-04-22 07:07
<b>MOT test number</b>	603899326622
<b>Result</b>	✓ Passed
<b>MOT #9</b>	2015-04-29 08:10
<b>MOT test number</b>	289759115115
<b>Result</b>	✓ Passed
<b>MOT #8</b>	2014-05-06 08:27
<b>MOT test number</b>	187456924178
<b>Result</b>	✓ Passed
<b>MOT #7</b>	2013-05-07 15:58
<b>MOT test number</b>	848067723164
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2012-05-05 12:03
<b>MOT test number</b>	106816922164
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2011-04-27 11:43
<b>MOT test number</b>	359347511143
<b>Result</b>	✓ Passed

**MOT #4** 2011-04-27 11:43**MOT test number** 236627211183**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2010-05-12 13:27**MOT test number** 972602130132**Result** ✓ Passed**MOT #2** 2010-05-08 12:36**MOT test number** 583388420151**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Rear brake caliper leaking (3.6.A.1)**MOT #1** 2009-05-09 11:04**MOT test number** 480819529149**Result** ✓ Passed**Notice** Cut nearside front and offside rear tyre not to cords



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
25 April 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	25 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 <b>LV06YKW</b>
Plate since	2019-06-29
Current registration	 <b>LV06YKW</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-05-20
Last registration	2024-04-25
Complete history	<a href="#">See info</a>



Registration #1	2006-05-20	23 mi
Registration #2	2009-05-09	15.971 mi
Registration #3	2010-05-08	21.779 mi
Registration #4	2010-05-12	21.779 mi
Registration #5	2011-04-27	27.405 mi
Registration #6	2012-05-05	33.677 mi
Registration #7	2013-05-07	37.946 mi
Registration #8	2014-05-06	41.363 mi
Registration #9	2015-04-29	43.533 mi
Registration #10	2016-04-22	45.161 mi
Registration #11	2016-05-20	45.161 mi
Registration #12	2016-05-20	45.161 mi
Registration #13	2016-05-20	45.161 mi
Registration #14	2016-05-20	45.161 mi
Registration #15	2016-05-20	45.161 mi
Registration #16	2016-05-20	45.161 mi
Registration #17	2016-05-20	45.161 mi
Registration #18	2016-05-20	45.161 mi
Registration #19	2016-05-20	45.161 mi
Registration #20	2016-05-20	45.161 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430812218