





report date: 2024-03-28

## General information

Make	MERCEDES-BENZ
Model	B-CLASS B150 SE
Colour	Blue
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	94 BHP
Max. torque	140 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg



CarCheck.co.uk page 1/12



FV56LYZ

report date: 2024-03-28

# Internet history

## Entry 1

Date 2021-07-12

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



## MOT history

MOT #13	2021-06-23 10:43
MOT test number	858541355073
Result	✓ Passed
Next expiry date	2022-06-22
MOT #12	2020-06-02 12:06
MOT test number	257765905754
Result	✓ Passed

MOT #11 2019-03-25 15:18 MOT test number 905862176044

**Result** ✓ Passed

Advice

Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10		2017-09-02 10:46
MOT test	number	612364726241
Result		✓ Passed
Advice	Nearside Rear Inner Uneven tyre wear	
Advice Parking brake lever has little reserve travel (3.1.6b)		
Advice	Offside Rear Inner Uneven tyre wear	

CarCheck.co.uk page 3/12



**MOT #9** 2017-09-01 14:43

**MOT test number** 258582727059

Result X Failed

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Rear Inner Uneven tyre wear

**Advice** Parking brake lever has little reserve travel (3.1.6b)

Fail Offside Front coil spring broken (2.4.C.1a)

**Advice** Nearside Rear Inner Uneven tyre wear

MOT #8 2016-07-28 09:21

**MOT test number** 189007568426

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #7 2015-06-05 09:28

**MOT test number** 728906055167

**Result** ✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2014-04-12 13:32

**MOT test number** 278822104134

Result \( \sqrt{Passed} \)

**Notice** Under-trays fitted obscuring some underside components

**Advice** Offside Lower Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)

CarCheck.co.uk page 4/12



MOT #5 2013-04-26 14:34

**MOT test number** 138826413190

**Result** ✓ Passed

**Advice** Tyre pressure monitoring system warning lamp does not illuminate (4.1.D.4)

**Notice** Some corrosion to rear brake disc's

MOT #4 2011-11-02 11:00

MOT test number 409346601326

Result \( \sqrt{Passed} \)

**Advice** Offside Rear coil spring corroded (2.4.C.1b)

**Advice** Nearside Rear coil spring corroded (2.4.C.1b)

MOT #3 2010-10-29 14:43

**MOT test number** 801692800363

**Result** ✓ Passed

MOT #2 2010-10-28 12:16

**MOT test number** 571071800364

Result X Failed

**Fail** Offside Front Front constant velocity joint gaiter split (2.5.C.1a)

CarCheck.co.uk page 5/12



FV56LYZ

report date: 2024-03-28

MOT #1 2009-11-02 10:00 **MOT test number** 442196909499 Result ✓ Passed **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Advice Rear Brake pad(s) wearing thin (3.5.1g) Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1

Date

Category

\_ \_

**Type** 

Damage 2
Date

Category

**Type** 



#### Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report <a href="https://example.com/here">here</a> .	
********	
********	
************	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-11-29
Last registration	2021-06-23
Complete history	See info



Registration #1	2006-11-29	28 mi
Registration #2	2009-11-02	44.426 mi
Registration #3	2010-10-28	60.202 mi
Registration #4	2010-10-29	60.216 mi
Registration #5	2011-11-02	76.328 mi
Registration #6	2013-04-26	84.014 mi
Registration #7	2014-04-12	85.245 mi
Registration #8	2015-06-05	90.712 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



## Car features

50225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1300 kg
Max. allowed weight	1835 kg

# Additional information

Fuel tank capacity	54
Fuel delivery	Multi-Point Injection
Number of doors	5
CarChack co. uk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	26692030227811