



report date: 2024-03-29

General information

|                     |                        |
|---------------------|------------------------|
| Make                | VOLVO                  |
| Model               | S40 D4 R-DESIGN        |
| Colour              | White                  |
| Year of manufacture | -                      |
| Top speed           | 134 mph                |
| 0 - 60 mph          | 8.2 seconds            |
| Gearbox             | 6 speed Semi-Automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 177 BHP             |
| Max. torque             | 400 Nm at 1.750 rpm |
| Cylinders               | 5                   |
| Fuel type               | Diesel              |
| Consumption city        | 35.8 mpg            |
| Consumption extra urban | 61.4 mpg            |
| Consumption combined    | 48.7 mpg            |



LABEL UNKNOWN



Internet history

Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-02-18                  |
| Pictures      | 17                          |
| Listing price | <a href="#">View report</a> |



source: [yesauto.com](#)

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-02-02                  |
| Pictures      | 1                           |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](#)



## MOT history

|                  |                  |
|------------------|------------------|
| MOT #12          | 2022-01-29 08:06 |
| MOT test number  | 478856731434     |
| Result           | ✓ Passed         |
| Next expiry date | 2023-01-28       |

|                 |                  |
|-----------------|------------------|
| MOT #11         | 2022-01-28 13:49 |
| MOT test number | 976465375507     |
| Result          | ✗ Failed         |

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

|                 |                  |
|-----------------|------------------|
| MOT #10         | 2020-05-14 15:36 |
| MOT test number | 597210006776     |
| Result          | ✓ Passed         |

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

|                 |                  |
|-----------------|------------------|
| MOT #9          | 2020-05-14 09:29 |
| MOT test number | 387812149908     |
| Result          | ✗ Failed         |

**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Exhaust emissions exceed manufacturer's specified limit 0.52 (8.2.2.2 (a))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

|                 |                  |
|-----------------|------------------|
| MOT #8          | 2019-04-09 14:42 |
| MOT test number | 722328240772     |
| Result          | ✓ Passed         |

**MOT #7**

2019-04-09 08:45

**MOT test number**

663131502179

**Result****✗ Failed**

- Advice** Offside Rear un even tread on inner edge
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm on inner (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #6**

2018-04-09 15:19

**MOT test number**

541954990392

**Result****✓ Passed**

- Advice** Rear both rear tyres out of shape on inner shoulders
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #5**

2017-04-07 09:10

**MOT test number**

682541183172

**Result****✓ Passed****MOT #4**

2017-04-05 09:30

**MOT test number**

390422708351

**Result****✗ Failed**

- Advice** Offside Rear Nail in tyre
- Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)



|                 |                  |
|-----------------|------------------|
| MOT #3          | 2016-04-12 11:50 |
| MOT test number | 162864377752     |
| Result          | ✓ Passed         |
| MOT #2          | 2015-04-13 15:46 |
| MOT test number | 527303705174     |
| Result          | ✓ Passed         |
| MOT #1          | 2013-09-24 09:59 |
| MOT test number | 138877463272     |
| Result          | ✓ Passed         |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |            |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2024-03-29 |
| Current registration |            |
| Plate since          | 2024-03-29 |

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 15                       |
| First mileage registration | 2010-09-30               |
| Last registration          | 2022-01-29               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2010-09-30 | 21 mi      |
| Registration #2  | 2013-09-24 | 35.959 mi  |
| Registration #3  | 2015-04-13 | 59.708 mi  |
| Registration #4  | 2016-04-12 | 76.701 mi  |
| Registration #5  | 2017-04-05 | 91.561 mi  |
| Registration #6  | 2017-04-07 | 91.612 mi  |
| Registration #7  | 2018-04-09 | 108.429 mi |
| Registration #8  | 2019-04-09 | 122.282 mi |
| Registration #9  | 2020-04-09 | 136.135 mi |
| Registration #10 | 2021-04-09 | 150.000 mi |
| Registration #11 | 2022-01-29 | 163.865 mi |
| Registration #12 | 2023-01-29 | 177.730 mi |
| Registration #13 | 2024-01-29 | 191.595 mi |
| Registration #14 | 2025-01-29 | 205.460 mi |
| Registration #15 | 2026-01-29 | 219.325 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 91%                             |
| Children       | 78%                             |
| Pedestrian     | 26%                             |
| Safety systems | 71%                             |
| Overall rating | 73%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1782 mm |
| Height              | 1447 mm |
| Length              | 4266 mm |
| Wheel base          | 2640 mm |
| Kerb weight         | 1469 kg |
| Max. allowed weight | 1900 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 60 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 2                |
| Number of seats    | 4                |

|               |        |
|---------------|--------|
| Engine number | 862339 |
|---------------|--------|