





report date: 2024-03-28

General information

Make	MASERATI
Model	GHIBLI DV6
Colour	Blue
Year of manufacture	2015
Top speed	155 mph
0 - 60 mph	6.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	275 BHP
Max. torque	600 Nm at 2.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 2


Date 2021-07-22

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 1

Date	2021-07-21

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-19
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	20
Total items failed	7

MOT #9	2023-07-20 13:23
MOT test number	683658084491
Result	✓ Passed
Next expiry date	2024-07-19
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #8 2023-07-20 13:23

MOT test number 694214486174

Result X Failed

Pass with rectificationOffside Front Inner Position lamp switch does not illuminate the front and rear position lamps with a single operation switch worked intermittently//when pushed// (4.2.2 (a))

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

CarCheck.co.uk page 3/13



MOT #7 2023-07-20 10:34

MOT test number 462157453447

Result X Failed

Fail Rear Position lamp not working (4.2.1 (a) (ii))

Advice Front Tyre worn close to legal limit/worn on edge both edges 235/50r18 (5.2.3 (e))

Fail Front Position lamp not working (4.2.1 (a) (ii))

Advice Front Tyre has a cut but not deep enough to reach the ply or cords both (5.2.3 (d) (i))

Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

Fail Position lamp switch does not illuminate the front and rear position lamps with a single operation (4.2.2 (a))

MOT #6 2022-07-05 11:15

MOT test number 213185493192

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Nail in tyre

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/13



MOT #5 2022-07-05 10:51

MOT test number 901622030162

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Rear Registration plate does not conform to the specified requirements (0.1 (d))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Front Registration plate does not conform to the specified requirements (0.1 (d))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Nail in tyre

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #4 2021-07-09 15:54

MOT test number 102430637422

Result
✓ Passed

Advice Coolant leak

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Tyre light on

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2019-12-18 16:25

MOT test number 953196302396

MOT #2 2018-09-10 12:14

MOT test number 403699155615

Result ✓ Passed

CarCheck.co.uk page 5/13



MOT #1 2018-09-10 09:31

MOT test number 727138583361

Result

X Failed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13




Damage history

Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra MASERATI salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this MASERATI? How many own MASERATI have? Check it in the premium report and see all owner registrations. Downloahere.	

2000000	

	More info >
Plate changes	
See in this check if this MASERATI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-04-23
Last registration	2023-07-20
Complete history	See info



Registration #1	2015-04-23	13 mi
Registration #2	2018-09-10	33.903 mi
Registration #3	2018-09-10	33.903 mi
Registration #4	2019-12-18	47.667 mi
Registration #5	2021-07-09	49.506 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		91.777 esi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71,777 es

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Adult	95%
Children	79%
Pedestrian	74%
Safety systems	81%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1945 mm
Height	1455 mm
Length	4971 mm
Wheel base	2998 mm
Kerb weight	1950 kg
Max. allowed weight	2500 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	136622

CarCheck.co.uk page 13/13