



report date: 2024-03-28

General information

|                     |                   |
|---------------------|-------------------|
| Make                | MAZDA             |
| Model               | 3 TAKARA          |
| Colour              | Blue              |
| Year of manufacture | 2009              |
| Top speed           | 109 mph           |
| 0 - 60 mph          | 12.6 seconds      |
| Gearbox             | 4 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 103 BHP             |
| Max. torque             | 145 Nm at 4.000 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 27.7 mpg            |
| Consumption extra urban | 44.1 mpg            |
| Consumption combined    | 36.2 mpg            |
| CO2 emission            | 183 g/km            |
| CO2 label               | I                   |





## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-01-16 |
| MOT pass rate      | 81 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 3          |
| Total advice items | 23         |
| Total items failed | 2          |

|                  |   |
|------------------|---|
| MOT #16          | 2024-01-10 12:24  |
| MOT test number  | 920824820946  |
| Result           | ✓ Passed  |
| Next expiry date | 2025-01-16  |
| Advice           | Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) |

|                         |   |
|-------------------------|---|
| MOT #15                 | 2024-01-10 12:24  |
| MOT test number         | 986234870742  |
| Result                  | ✗ Failed  |
| Pass with rectification | Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))              |
| Advice                  | Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) |

|                 |  |
|-----------------|--|
| MOT #14         | 2023-01-06 11:39   |
| MOT test number | 416480750803   |
| Result          | ✓ Passed   |
| Advice          | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))  |
| Advice          | Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))                          |
| Advice          | Offside Rear Tyre worn close to legal limit/worn on edge Inner edge worn tread depth 2.5mm (5.2.3 (e)) |
| Advice          | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))   |

**MOT #13** 2022-01-07 11:37**MOT test number** 377420463019**Result** ✓ Passed**MOT #12** 2021-01-05 11:37**MOT test number** 806794986067**Result** ✓ Passed**MOT #11** 2020-01-08 13:18**MOT test number** 260380167317**Result** ✓ Passed

**Advice** Nearside Rear Brake hose has slight corrosion to ferrule Cant completely inspect due to rubber sheath. (1.1.12 (f) (i))

**Advice** Nearside Front Outer tyre wearing thin on edge

**Advice** Offside Rear Brake hose has slight corrosion to ferrule Cant completely inspect due to rubber sheath. (1.1.12 (f) (i))

**Advice** Rear exhaust bracket corroding

**MOT #10** 2019-01-10 16:03**MOT test number** 731362845939**Result** ✓ Passed**MOT #9** 2019-01-10 12:44**MOT test number** 374045497737**Result** ✗ Failed

**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #8** 2018-01-08 11:39**MOT test number** 436444934544**Result** ✓ Passed

**MOT #7** 2017-01-12 09:49**MOT test number** 239528847534**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2016-01-13 14:02**MOT test number** 199016777692**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2016-01-13 12:35**MOT test number** 596083288717**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** All tyres very perished**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2015-01-13 11:35**MOT test number** 606423415014**Result** ✓ Passed**Notice** Lower arms, rear bushes perishing**Notice** Front brake pads wearing low



|                 |   |
|-----------------|---|
| MOT #3          | 2014-01-13 14:51                          |
| MOT test number | 175683914028                              |
| Result          | ✓ Passed                                  |
| Notice          | N/s/f brake pad appears to be wearing low |

|                 |                  |
|-----------------|------------------|
| MOT #2          | 2013-01-09 14:24 |
| MOT test number | 589549503015     |
| Result          | ✓ Passed         |

|                 |   |
|-----------------|---|
| MOT #1          | 2012-01-17 16:43  |
| MOT test number | 369867612035  |
| Result          | ✓ Passed  |
| Advice          | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
16 January 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 April             |
| <b>Days left</b>        | 338                             |
| <b>MOT expiry date</b>  | 16 January 2025                 |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 48         |
| <b>Band</b>                                    | I          |
| <b>Single payment (12 months)</b>              | £ 320,00,- |
| <b>Single six month payment</b>                | £ 176,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 336,00,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |            |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2019-09-28 |
| Current registration |            |
| Plate since          | 2019-09-28 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 17                       |
| First mileage registration | 2009-01-16               |
| Last registration          | 2024-01-10               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2009-01-16 | 20 mi     |
| Registration #2  | 2012-01-17 | 22.289 mi |
| Registration #3  | 2013-01-09 | 25.604 mi |
| Registration #4  | 2014-01-13 | 28.421 mi |
| Registration #5  | 2015-01-13 | 31.104 mi |
| Registration #6  | 2016-01-13 | 33.775 mi |
| Registration #7  | 2016-01-13 | 33.775 mi |
| Registration #8  | 2017-01-12 | 36.459 mi |
| Registration #9  | 2018-01-08 | 38.997 mi |
| Registration #10 | 2019-01-08 | 41.535 mi |
| Registration #11 | 2020-01-08 | 44.073 mi |
| Registration #12 | 2021-01-08 | 46.611 mi |
| Registration #13 | 2022-01-08 | 49.149 mi |
| Registration #14 | 2023-01-08 | 51.687 mi |
| Registration #15 | 2024-01-10 | 54.225 mi |
| Registration #16 | 2024-01-10 | 54.225 mi |
| Registration #17 | 2024-01-10 | 54.225 mi |

More info >



Safety ratings

|             |                                 |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆                           |
| Video       | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1755 mm |
| Height              | 1465 mm |
| Length              | 4440 mm |
| Wheel base          | 2640 mm |
| Kerb weight         | 1290 kg |
| Max. allowed weight | 1750 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Engine number      | Z6 768662             |