



AJ09VKX

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF GT TDI
Colour	Blue
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-06-07
Pictures	21
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-07-13
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	15
Total items failed	10

MOT #15 2023-07-14 10:33**MOT test number** 392091269537**Result** Passed**Next expiry date** 2024-07-13**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14** 2022-07-02 09:20**MOT test number** 877894110555**Result** Passed**MOT #13** 2021-06-10 11:50**MOT test number** 752534117199**Result** Passed**MOT #12** 2020-06-16 12:00**MOT test number** 445404686142**Result** Passed

**MOT #11** 2019-06-26 15:57**MOT test number** 608337402535**Result** ✓ Passed**MOT #10** 2019-06-26 08:30**MOT test number** 137679193501**Result** ✓ Passed**MOT #9** 2018-06-27 14:44**MOT test number** 820241067176**Result** ✓ Passed**Advice** Front windscreen damaged**MOT #8** 2018-06-26 12:38**MOT test number** 280413362492**Result** ✗ Failed**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front windscreen damaged**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #7** 2017-06-13 14:46**MOT test number** 867248752458**Result** ✓ Passed**Advice** Emissions too clean for reading**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2017-06-13 08:35**MOT test number** 297645546842**Result** ✗ Failed

- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Emissions too clean for reading
- Fail** Offside Registration plate lamp not working (1.1.C.1d)

MOT #5 2016-07-11 12:52**MOT test number** 670049547141**Result** ✓ Passed**MOT #4** 2015-03-17 13:08**MOT test number** 555756275092**Result** ✓ Passed

- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #3 2015-03-11 17:09**MOT test number** 696100175050**Result** ✗ Failed

- Fail** Offside Headlamp aim not tested (1.8.A.1c)
- Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2014-03-21 11:33
MOT test number	458710384028
Result	✓ Passed
<div>Notice</div> Unable to fully inspect underside floor area including some front steering and suspension components due to plastic under covers fitted	

MOT #1	2013-02-25 09:16
MOT test number	105136953445
Result	✓ Passed
<div>Notice</div> N/s wiper blade deteriorating	



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2024

✓

MOT

Expires:
13 July 2024

Tax status	Expired at 1 April 2024
Days left	28 days too late
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 AJ09VKX
Plate since	2024-03-29
Current registration	 AJ09VKX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-04
Last registration	2023-07-14
Complete history	See info



Registration #1	2009-06-04	25 mi
Registration #2	2013-02-25	57.040 mi
Registration #3	2014-03-21	62.916 mi
Registration #4	2015-03-11	68.620 mi
Registration #5	2015-03-17	68.640 mi
Registration #6	2016-07-11	76.242 mi
Registration #7	2017-06-13	86.062 mi
Registration #8	2017-06-13	86.062 mi
Registration #9	2018-06-26	98.907 mi
Registration #10	2019-06-26	111.752 mi
Registration #11	2020-06-26	124.597 mi
Registration #12	2021-06-26	137.442 mi
Registration #13	2022-06-26	150.287 mi
Registration #14	2023-06-26	163.132 mi
Registration #15	2024-06-26	175.977 mi
Registration #16	2025-06-26	188.822 mi
Registration #17	2026-06-26	201.667 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1299 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CBA 494126