



report date: 2024-03-30

General information

Make	CITROEN
Model	C4 PICASSO BLUEHDI FEEL S/S EAT6
Colour	Blue
Year of manufacture	2017
Top speed	117 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	A






Internet history

Entry 1

Date	2022-04-21
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-19
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	13
Total items failed	8

MOT #9	2024-03-08 16:26
MOT test number	782627739726
Result	✓ Passed
Next expiry date	2025-03-19
Advice	Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

MOT #8	2024-03-08 09:12
MOT test number	294346515852
Result	✗ Failed
Advice	Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7	2023-03-20 11:18
MOT test number	884351487813
Result	✓ Passed
Advice	Nearside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #6**

2023-03-17 13:16

**MOT test number**

738871254357

**Result****✗ Failed****Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Rear Outer Brake pad(s) incorrectly mounted lining adrift from pad (1.1.13 (c))**Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5**

2022-03-12 12:17

**MOT test number**

692860885509

**Result****✓ Passed****MOT #4**

2022-03-12 10:27

**MOT test number**

884848534471

**Result****✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn inner edge. 205/55.17 (5.2.3 (e))**Fail** Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Advice** Nearside Front Nail in tyre**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 205/55.17 (5.2.3 (e))

**MOT #3** 2021-03-06 10:46**MOT test number** 797683772121**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge only 205/55/17 (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge plus nail in tyre (5.2.3 (e))**MOT #2** 2021-03-06 10:46**MOT test number** 252820383445**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge only 205/55/17 (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge plus nail in tyre (5.2.3 (e))**MOT #1** 2020-03-07 09:49**MOT test number** 808352771803**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
19 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	19 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 <b>KV17FRF</b>
Plate since	2019-09-29
Current registration	 <b>KV17FRF</b>
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-03-20
Last registration	2024-03-08
Complete history	<a href="#">See info</a>



Registration #1	2017-03-20	19 mi
Registration #2	2020-03-07	43.845 mi
Registration #3	2021-03-06	52.400 mi
Registration #4	2021-03-06	52.400 mi
Registration #5	2022-03-12	56.892 mi
Registration #6	2022-03-12	56.892 mi
Registration #7	2023-03-08	59.377 mi
Registration #8	2023-03-08	59.377 mi
Registration #9	2023-03-08	59.377 mi
Registration #10	2023-03-08	59.377 mi
Registration #11	2024-03-08	59.377 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1826 mm
Height	1625 mm
Length	4428 mm
Wheel base	2785 mm
Kerb weight	1320 kg
Max. allowed weight	1975 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHD3066007