





General information

Make	VOLVO
Model	V50 D DRIVE S
Colour	Gold
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg





Internet history

Entry 1

Date

2021-07-24

Pictures

Listing price

View report

6









source: autotrader.co.uk



MOT history

MOT #13	2022-07-22 11:42
MOT test number	779824023422
Result	✓ Passed
Next expiry date	2023-07-22
Advice Rear Tyre worn close to legal limit/worn on edge both sides on inne	er edges (5.2.3 (e))

MOT #12	2022-07-22 07:47	
MOT test number	332275127912	
Result	🗙 Failed	
Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))		
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))		
Advice Rear Tyre worn close to legal limit/worn on edge both sides on inner edges (5	5.2.3 (e))	

MOT #11	2021-07-23 15:53
MOT test number	541466848084
Result	✓ Passed
MOT #10	2020-00-05 12.08

MOT #10	2020-09-05 12:08
MOT test number	563654530005
Result	✓ Passed

MOT #9		2020-09-05 12:08
MOT test number		675295096962
Result		🗙 Failed
Pass with rectification	Front Windscreen wiper not working both (3.4 (a))	

MOT #8	2019-04-27 10:27
MOT test number	869284093261
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #7		2018-04-27 10:04
MOT test	number	471024739713
Result		✓ Passed
Advice	Registration plate deteriorated but not likely to be misread both (6.3.1d)	
MOT #6		2017-04-22 09:26
MOT test	number	421615662124
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5		2016-04-23 15:41
MOT test	number	160734184103
Result		✓ Passed
Advice	Nearside Front Inner Tyre worn close to the legal limit adge (4.1.E.1)	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Offside Front Inner Tyre worn close to the legal limit adge (4.1.E.1)	

Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #4	2015-04-23 16:34
MOT test number	367083015182
Result	✓ Passed

MOT #3	2014-04-05 09:47
MOT test number	117465194488
Result	✓ Passed

Advice





MOT #2	2013-03-02 11:52
MOT test number	577891863004
Result	✓ Passed
Advice Nearside Inner Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Inner Rear Brake pad(s) wearing thin (3.5.1g)	
MOT #1	2012-03-07 12:35

	2012-03-07 12:35
MOT test number	865307962084
Result	✓ Passed
Advice Parking brake lever has little reserve travel (3.1.6b)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Date	1. the second se
Category	ante
Туре	

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-04-09
Last registration	2022-07-22
Complete history	See info



Registration #1	2009-04-09	7 mi
Registration #2	2012-03-07	68.327 mi
Registration #3	2013-03-02	93.935 mi
Registration #4	2014-04-05	103.722 mi
Registration #5	2015-04-23	114.496 mi
Registration #6	2016-04-23	122.451 mi
Registration #7	2017-04-22	127.434 mi
Registration #8	2018-04-27	132.671 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1408 kg
Max. allowed weight	1880 kg
Additional information	
Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/11