



report date: 2024-03-28

General information

Make	MINI
Model	MINI ONE
Colour	White
Year of manufacture	2011
Top speed	116 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D





MOT history

MOT expiry date	2025-02-24
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #13	2024-02-23 11:21
MOT test number	712104757796
Result	✓ Passed
Next expiry date	2025-02-24

MOT #12	2023-02-25 09:46
MOT test number	138316173096
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11	2022-01-27 13:00
MOT test number	388246911365
Result	✓ Passed

MOT #10	2022-01-26 16:09
MOT test number	170980045284
Result	✗ Failed
Fail	Nearside Front Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))
Minor	Brake fluid warning lamp illuminated (1.1.10 (f))

**MOT #9** 2021-01-11 16:23**MOT test number** 423404394199**Result** ✓ Passed**MOT #8** 2020-02-25 12:06**MOT test number** 263054479776**Result** ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7 2019-02-12 15:51**MOT test number** 647935452214**Result** ✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2019-02-12 12:13**MOT test number** 267029693916**Result** ✗ Failed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #5 2018-02-20 16:38**MOT test number** 436651702857**Result** ✓ Passed

Advice Nearside Rear tyre cracking on inner wall

MOT #4 2017-02-15 08:43**MOT test number** 294699293881**Result** ✓ Passed



MOT #3	2016-02-26 17:20
MOT test number	807346285300
Result	✓ Passed
MOT #2	2015-02-17 14:38
MOT test number	448578445052
Result	✓ Passed
MOT #1	2014-02-20 09:47
MOT test number	405631454028
Result	✓ Passed
<div>Notice Front tyres scrubbed</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 February 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	24 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YG11BMY
Plate since	2019-09-28
Current registration	YG11BMY
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-01
Last registration	2024-02-23
Complete history	See info



Registration #1	2011-03-01	7 mi
Registration #2	2014-02-20	11.086 mi
Registration #3	2015-02-17	13.280 mi
Registration #4	2016-02-26	14.922 mi
Registration #5	2017-02-15	17.151 mi
Registration #6	2018-02-20	19.082 mi
Registration #7	2019-02-12	20.970 mi
Registration #8	2020-02-20	22.877 mi
Registration #9	2021-02-20	24.777 mi
Registration #10	2022-02-20	26.677 mi
Registration #11	2023-02-20	28.577 mi
Registration #12	2024-02-20	30.477 mi
Registration #13	2025-02-20	32.377 mi
Registration #14	2026-02-20	34.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	B410I896