





report date: 2024-03-29

#### General information

Make	RENAULT
Model	ZOE DYNAMIQUE INTENS
Colour	White
Year of manufacture	2014
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

### Engine & fuel consumption

Power	87 BHP
Max. torque	220 Nm at 2.500 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/13



report date: 2024-03-29

### Internet history

#### Entry 2

Date 2022-01-27	
-----------------	--

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-09-18
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-01
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	15
Total items failed	11

MOT #12	2024-01-26 15:28
MOT test number	737518422425
Result	<b>✓</b> Passed
Next expiry date	2025-02-01
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #11	2024-01-26 10:43
MOT test number	149384674419
Result	<b>X</b> Failed
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Fail Offside Front Tyre has ply or cords exposed 195/55/16 (5.2.3 (d) (ii))	
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number
706119672061

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm (5.2.3 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

Nearside Front Tyre worn close to legal limit/worn on edge Worn to 3mm and worn on edges (5.2.3 (e))

2023-01-30 10:16 **MOT #9 MOT** test number 325406649744 Result × Failed Windscreen washer provides insufficient washer liquid Empty (3.5 (a)) Pass with rectification **Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn to 3mm and worn on edges (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm (5.2.3 (e)) Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e)) **Advice** Vehicles internal headlight adjuster altered to recheck lights 4

MOT #8	2022-02-02 15:14
MOT test number	818230059969
Result	✓ Passed
MOT #7	2022-01-31 14:30
MOT test number	106896540249
Result	<b>×</b> Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6 2021-10-20 09:31

**MOT test number** 713421392088

**Result** ✓ Passed

MOT #5 2021-10-18 12:01

**MOT test number** 202790088286

**Result** ★ Failed

**Fail** Nearside Front Macpherson strut insecurely attached coil spring not fitting in top strut bearing properly (5.3.3 (a) (i))

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #4 2020-10-13 15:03

**MOT test number** 917966635770

**Result** 
✓ Passed

MOT #3 2020-10-13 12:03

**MOT test number** 752456656743

**Result** X Failed

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #2 2019-10-05 10:11

**MOT test number** 512575191880

Result \( \sqrt{Passed} \)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1

MOT test number

194903185318

Result

Advice Offside Front tyre sidewall slightly perished

2017-10-18 11:55

✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

#### Tax & MOT check



Days left 279

MOT expiry date 1 February 2025

Full MOT history See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

$\alpha$	vner	hi	cto	200
$\cup$	viiei	ш	SIL	ЯΝ

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
HARMAN CONTRACTOR CONT	
THE STREET STREE	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-10-31
Last registration	2024-01-26
Complete history	See info



Registration #1	2014-10-31	10 mi
Registration #2	2017-10-18	8.821 mi
Registration #3	2019-10-05	23.530 mi
Registration #4	2020-10-13	28.955 mi
Registration #5	2020-10-13	28.955 mi
Registration #6		11.777 es
Registration #7	2021-10-18	36.564 mi
Registration #8	2021-10-20	36.564 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es
Registration #13		11.177 mi
Registration #14		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

## Safety ratings

NCAP rating	****
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



## Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1943 kg

## Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/2