





General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Silver
Year of manufacture	2003
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg
CO2 emission	259 g/km
CO2 label	М







Internet history

Entry	1

Date Pictures 2022-01-16

10

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-27
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	18
Total items failed	13

MOT #23	2023-10-28 10:41
MOT test number	886467651221
Result	✓ Passed
Next expiry date	2024-10-27
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge	(5.2.3 (e))
Advice Nearside Front Tyre worn close to legal limit/worn on edge	e (5.2.3 (e))

MOT #22

2022-10-14 11:12

MOT test I	number	597846625741
Result		✓ Passed
Advice	Fluid leak, but not excessive coolant (8.4.1 (a) (i))	
Advice	Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	





MOT #21		2021-08-17 11:07
MOT test	number	262335701511
Result		✓ Passed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect	(5.3.2 (b))
Advice	Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))	
Advice	Rear shock absorbers corroded both	
Advice	Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))	
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	
Advice	Front Brake disc worn, but not excessively both (1.1.14 (a) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #20	2020-08-18 16:02
MOT test number	848920836783
Result	✓ Passed

MOT #19	2019-09-03 13:30
MOT test number	320385743115
Result	✓ Passed

MOT #18	2019-09-02 09:20
MOT test number	729594608127
Result	🗙 Failed
Fail Offside Rear Brake pipe leaking on an air braking system (1.1.11 (b) (i))	

MOT #17	2018-08-07 09:05
MOT test number	808231856355
Result	✓ Passed





MOT #16	2018-07-31 10:37
MOT test number	523488060378
Result	🗙 Failed
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))
FailNearside Rear Lower Anti-roll bar linkage ball joint dust cover no longer prevents the (5.3.4 (b) (ii))	າe ingress of dirt
Fail Offside Rear Lower Anti-roll bar linkage ball joint dust cover no longer prevents the (5.3.4 (b) (ii))	ingress of dirt
FailOffside Rear Outer Suspension rod ball joint dust cover no longer prevents the ingr(b) (ii))	ess of dirt (5.3.4
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (z))
FailNearside Rear Upper Anti-roll bar linkage ball joint dust cover no longer prevents the (5.3.4 (b) (ii))	ne ingress of dirt
Fail Offside Rear Upper Anti-roll bar linkage ball joint dust cover no longer prevents the (5.3.4 (b) (ii))	ingress of dirt
Fail (b) (ii))Nearside Rear Outer Suspension rod ball joint dust cover no longer prevents the ing	gress of dirt (5.3.4

MOT #15	2017-08-02 12:59
MOT test number	274472284886
Result	Passed

MOT #14	2017-08-02 12:59
MOT test number	236069819464
Result	× Failed
Pass with rectification	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Pass with rectification	Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
Pass with rectification the ply or cords (4.1.D.1a)	Offside Front Tyre has a cut in excess of the requirements deep enough to reach
Pass with rectification the ply or cords (4.1.D.1a)	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach

MOT #13	2016-08-19 08:46
MOT test number	891471793913
CarCheck.co.uk	page 5/14

Result







MOT #12	2015-09-01 14	:45
MOT test number	2171137825	
Result	V Pass	sed
MOT #11	2014-07-25 12	:20
MOT test number	8859960042	296
Result	V Pass	sed
MOT #10	2013-07-17 09	:54
MOT test number	4299683931	100
Result	V Pass	sed
		_
MOT #9	2013-07-17 09	:54
MOT test number	3388381931	192
Result	🗙 Fai	led
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (8.2.3)	
MOT #8	2012-07-27 14	:38
MOT test number	7078796022	255
Result	V Pass	sed
		_
MOT #7	2011-06-06 11	
MOT test number	7261474513	11
Result	V Pass	sed
MOT #6	2010-06-10 09	:59

MOT test number	752731660115
Result	✓ Passed





MOT #5	2009-06-09 11:30
MOT test number	123010869170
Result	✓ Passed
MOT #4	2008-06-05 12:26
MOT test number	682637058122
Result	✓ Passed
MOT #3	2007-06-01 09:53
MOT test number	531692757175
Result	✓ Passed
MOT #2	2006-05-19 10:00
MOT test number	431619336134
Result	✓ Passed
MOT #1	2006-05-18 16:52
MOT test number	990208436199
Result	🗙 Failed
Notice Nearside front and Offside front wiper blades are split.	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	



Tax & MOT check

✓ Taxed	√ мот
Tax due: 1 May 2024	Expires: 27 October 2024
Tax status	Valid until 1 May
Days left	2
MOT expiry date	27 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plat	tes.
Number of plates	7
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-05-30
Last registration	2023-10-28
Complete history	See info



Registration #1	2003-05-30	26 mi
Registration #2	2006-05-18	27.915 mi
Registration #3	2006-05-19	27.915 mi
Registration #4	2007-06-01	33.737 mi
Registration #5	2008-06-05	38.969 mi
Registration #6	2009-06-09	42.262 mi
Registration #7	2010-06-10	45.516 mi
Registration #8	2011-06-06	47.387 mi
Registration #9	2012-07-27	49.873 mi
Registration #10	2013-07-17	51.251 mi
Registration #11	2014-07-25	53.263 mi
Registration #12	2015-09-01	55.294 mi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		10.200 est
Registration #17		11.777 mi
Registration #17 Registration #18		11.227 est
		11.227 est 11.227 est 11.227 est
Registration #18		00.000 em
Registration #18 Registration #19		01.000 est 01.000 est 01.000 est 01.000 est 01.000 est
Registration #18 Registration #19 Registration #20		20.222 est 0.222 est 0.222 est 0.222 est 0.222 est 0.222 est
Registration #18 Registration #19 Registration #20 Registration #21		10.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		20,222 est 20,222 est 20,222 est 20,222 est 20,222 est 20,222 est 20,222 est







Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Additional information	
Fuel tank capacity	69 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	335539378FB