





report date: 2024-03-29

### General information

Make	HONDA
Model	CIVIC I-DTEC SE PLUS NAVI
Colour	Black
Year of manufacture	2016
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	118 BHP
Engine capacity	1.597 сс
Cylinders	4
Fuel type	Diesel
CO2 emission	94 g/km
CO2 label	А



CarCheck.co.uk page 1/11



### Internet history

### Entry 2

Date 2021-09-23

Pictures 1

Listing price <u>View report</u>



source: cargurus.co.uk

#### Entry 1

Date	2021-02-25
Pictures	27

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



## MOT history

MOT expiry date	2024-11-07
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	9
Total items failed	5

MOT #9	2023-11-08 17:12	
MOT test number	395894900230	
Result	✓ Passed	
Next expiry date	2024-11-07	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		

MOT #8		2022-10-20 12:51
MOT test i	number	517224907731
Result		✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge and outer (5.2.3 (e)	)

MOT #7	2022-10-20 10:38
MOT test number	578057610487
Result	🗙 Failed
Fail Nearside Front Headlamp aim not tested (4.1.2 (b))	
Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Offside Front Headlamp aim too high (4.1.2 (a))	
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge and outer (5.2.3 (e)	))

CarCheck.co.uk page 3/11



MOT #6 2021-10-21 16:01
MOT test number 558277574127

Result 

Passed

**MOT #5** 2021-03-03 10:48

**MOT test number** 775393224033

**Result** ✓ Passed

MOT #4 2021-02-27 13:16

**MOT test number** 603487537672

Result X Failed

Fail Offside Front Brake pad(s) incorrectly mounted (1.1.13 (c))

MOT #3 2020-06-26 14:02

**MOT test number** 932972276694

Result \rightarrow Passed

MOT #2 2019-04-15 12:23

MOT test number 667380365149

Advice Nearside Front Outer Small cut in tyre sidewall, not exposing cords or ply

**Advice** Items removed from driver's view prior to test

**MOT #1** 2019-04-15 12:23

**MOT test number** 318325596857

**Result** X Failed

**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

**Advice** Items removed from driver's view prior to test

Advice Nearside Front Outer Small cut in tyre sidewall, not exposing cords or ply

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	7 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable


CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	NIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-05-06
Last registration	2023-11-08
Complete history	See info



Registration #1	2016-05-06	28 mi
Registration #2	2019-04-15	51.383 mi
Registration #3	2019-04-15	51.383 mi
Registration #4	2020-06-26	68.561 mi
Registration #5		11.777 es
Registration #6	2021-02-27	70.252 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	****
Adult	94%
Children	83%
Pedestrian	69%
Safety systems	86%
Overall rating	86%
Video	see crash video



# Dimensions & weight

Width	1770 mm
Height	1470 mm
Length	4370 mm
Wheel base	2595 mm
Kerb weight	1425 kg
Max. allowed weight	1870 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	N16A14002051

CarCheck.co.uk page 11/11