



report date: 2024-03-29

General information

Make	VAUXHALL
Model	TIGRA SXI 16V TWINPORT
Colour	Blue
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg







LABEL UNKNOWN



Internet history

Entry 2


Date	2021-09-19
Pictures	39
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-16
Pictures	34
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT #10	2021-06-25 13:46
MOT test number	222833525097
Result	✓ Passed
Next expiry date	2022-06-24
Advice	Underbody components corroded, not seriously weakened
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9	2021-06-24 13:20
MOT test number	118763196633
Result	✗ Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources 1 of 2 (4.7.1 (b) (i))
Advice	Underbody components corroded, not seriously weakened
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2015-11-30 11:55**MOT test number** 969820847153**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 3.0mm/wearing on edges and perishing (4.1.E.1)**Advice** Rear brake fluctuating, but not excessively (3.7.B.3)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)**Advice** Engine coolant level low**MOT #7** 2014-06-10 10:44**MOT test number** 696761164170**Result** ✓ Passed**Notice** Offside wiper split**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside front tyre**MOT #6** 2014-06-09 13:35**MOT test number** 379000664160**Result** ✗ Failed**Notice** Nail in nearside front tyre**Fail** Offside Rear Brake cable has wires broken and is significantly weakened (3.5.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside wiper split**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #5** 2013-03-11 16:16**MOT test number** 225490773003**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Slight blow from exhaust back box join**MOT #4** 2013-03-11 13:08**MOT test number** 128830373030**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Slight blow from exhaust back box join**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2012-04-05 08:14**MOT test number** 966536692024**Result** ✓ Passed**MOT #2** 2011-07-09 12:23**MOT test number** 909420891107**Result** ✓ Passed**MOT #1** 2010-06-23 14:03**MOT test number** 544144170138**Result** ✓ Passed**Notice** Nearside rear tyre on 3mm



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KE07NMD
Plate since	2019-06-29
Current registration	 KE07NMD
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2007-07-21
Last registration	2021-06-25
Complete history	See info



Registration #1	2007-07-21	10 mi
Registration #2	2010-06-23	36.574 mi
Registration #3	2011-07-09	50.532 mi
Registration #4	2012-04-05	56.272 mi
Registration #5	2013-03-11	72.646 mi
Registration #6	2013-03-11	72.646 mi
Registration #7	2014-06-09	77.055 mi
Registration #8	2015-06-25	77.055 mi
Registration #9	2016-06-25	77.055 mi
Registration #10	2017-06-25	77.055 mi
Registration #11	2018-06-25	77.055 mi
Registration #12	2019-06-25	77.055 mi
Registration #13	2021-06-25	77.055 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1753 mm
Height	1413 mm
Length	4288 mm
Wheel base	2614 mm
Kerb weight	1180 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	19KX6550