



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG TDI ALTITUDE
Colour	Blue
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	172 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.461 cc
Cylinders	5
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.0 mpg
CO2 emission	275 g/km
CO2 label	M





Internet history

Entry 2

Date	2022-03-31
Pictures	47
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-17
Pictures	9
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



## MOT history

MOT expiry date	2022-11-15
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	48
Total items failed	0

MOT #15	2021-11-16 12:36
MOT test number	453753616985
Result	✓ Passed
Next expiry date	2022-11-15

MOT #14	2021-11-15 10:10
MOT test number	238448301584
Result	✗ Failed
<b>DA</b> NGEROUS Stop lamp(s) all not working (4.3.1 (a) (iii))	

MOT #13	2020-09-01 09:27
MOT test number	791322220026
Result	✓ Passed
<b>Advice</b> Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #12	2020-08-27 15:22
MOT test number	635439079190
Result	✗ Failed
<b>Advice</b> Engine covers and under trays fitted obscuring some components	
<b>MAJOR</b> Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
<b>Advice</b> Coil springs corroded	



MOT #11	2020-08-26 09:33
MOT test number	818428334285
Result	✗ Failed
Advice	Coil springs corroded
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside rear and offside front brake pad wiring broken
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Brakes require further inspection
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Engine covers and under trays fitted obscuring some components
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #10

2019-09-18 08:17

MOT test number

547816657780

Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Coil springs corroded	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Brakes require further inspection	
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Engine covers and under trays fitted obscuring some components	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

**MOT #9**

2019-09-05 16:31

**MOT test number**

522164833583

**Result****✗ Failed**

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Body component damaged and likely to cause injury wing mirror cover (6.2.1 (a) (i))
- Advice** Engine covers and under trays fitted obscuring some components
- MAJOR** Offside Headlamp insecure (4.1.1 (c))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- DANGEROUS** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))
- MAJOR** Front Bumper insecure (6.1.4 (a) (i))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Minor** Rear Position lamp insecure (4.2.1 (c) (i))
- Advice** Coil springs corroded
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Brakes require further inspection
- MAJOR** Nearside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))
- Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))



<b>MOT #8</b>	2018-08-21 15:09
---------------	------------------

<b>MOT test number</b>	377177876894
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2017-09-05 14:15
---------------	------------------

<b>MOT test number</b>	951328662864
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2016-09-05 11:17
---------------	------------------

<b>MOT test number</b>	698146499178
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Screw in n/s front tyre
---------------	-------------------------

<b>MOT #5</b>	2015-07-22 07:36
---------------	------------------

<b>MOT test number</b>	735405367420
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2014-07-02 12:42
---------------	------------------

<b>MOT test number</b>	987133884188
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2013-07-06 10:33
---------------	------------------

<b>MOT test number</b>	427487283124
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2012-07-06 10:11
---------------	------------------

<b>MOT test number</b>	218128882464
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #1	2011-07-07 15:20
MOT test number	219488881434
Result	✓ Passed





Tax & MOT check

✕  
Untaxed

Tax expired:  
26 February 2022

✕  
MOT

Expired:  
15 November 2022

Tax status	Expired at 26 February 2022
Days left	793 days too late
MOT expiry date	15 November 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-07-07
Last registration	2021-11-16
Complete history	<a href="#">See info</a>



Registration #1	2008-07-07	16 mi
Registration #2	2011-07-07	24.721 mi
Registration #3	2012-07-06	32.558 mi
Registration #4	2013-07-06	37.516 mi
Registration #5	2014-07-02	40.828 mi
Registration #6	2015-07-22	59.365 mi
Registration #7	2016-09-05	71.884 mi
Registration #8	2017-09-05	83.839 mi
Registration #9	2018-08-21	96.208 mi
Registration #10	2019-05-20	101.277 mi
Registration #11	2019-05-20	101.277 mi
Registration #12	2019-05-20	101.277 mi
Registration #13	2019-05-20	101.277 mi
Registration #14	2019-05-20	101.277 mi
Registration #15	2019-05-20	101.277 mi
Registration #16	2019-05-20	101.277 mi
Registration #17	2019-05-20	101.277 mi
Registration #18	2019-05-20	101.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2230 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2510 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

---

**Number of seats**

5

**Engine number**

BPE 011351

---