






### General information

Make	MERCEDES
Model	SL 500
Colour	Silver
Year of manufacture	2002
Top speed	155 mph
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	306 BHP
Max. torque	460 Nm at 2.700 rpm
Engine capacity	4.966 cc
Cylinders	8
Fuel type	Petrol
Consumption city	14.8 mpg
Consumption extra urban	30.7 mpg
Consumption combined	22.2 mpg
CO2 emission	304 g/km
CO2 label	M



CarCheck.co.uk page 1/13



## Internet history

## Entry 3

Date 2022-01-03

Pictures 27

Listing price <u>View report</u>









source: yesauto.com

Entry 2

Date	2021-02-02
Pictures	10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2021-02-02
Pictures	1

Listing price <u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

2024-04-19
81 %
17
4
25
8
2023-04-20 16:05
891654991699
<b>✓</b> Passed
2024-04-19
2021-11-18 15:01
129220578000
✓ Passed
2020-11-20 13:16
307172984508
✓ Passed
2010 11 14 00 00
2019-11-14 09:08 145024516646
143024310040 ✓ Passed
<b>→</b> rasseu
2010 11 22 00 20
2018-11-22 09:30
587218896871

CarCheck.co.uk page 3/13



MOT #16 2017-11-14 11:37 **MOT** test number 956339238257 Result ✓ Passed **MOT #15** 2016-11-18 10:16 **MOT test number** 239118583776 ✓ Passed Result **MOT #14** 2015-12-09 09:09 **MOT test number** 148547815973 Result ✓ Passed MOT #13 2014-10-16 11:11 458269284266 **MOT** test number Result ✓ Passed **MOT #12** 2013-10-21 09:05 **MOT test number** 669694093235 Result ✓ Passed

MOT #11	2013-10-11 10:40
MOT test number	856444883253
Result	<b>×</b> Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 4/13



MOT #10		2012-10-24 11:11
MOT test	number	218788992260
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Temporary fuel cap fitted	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	

MOT #9		2011-09-30 11:17
MOT test	number	335253671409
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	


MOT #8		2010-10-05 14:50
MOT test	number	184018570248
Result		✓ Passed
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
Notice	Temporary fuel cap fitted	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/13



**19JAY** 

report date: 2024-03-28



MOT #6	2009-10-05 17:07
MOT test number	582088179246
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)  Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2009-10-05 11:55
MOT test number	320958179466
Result	<b>×</b> Failed
Fail Nearside Side repeater not working (1.4.A.2c)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4		2007-10-05 15:58
MOT test numb	per	281238177241
Result		<b>✓</b> Passed
Advice Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)		

CarCheck.co.uk page 6/13



.....

MOT #3 2007-09-28 10:23

**MOT test number** 551171277206

**Result** X Failed

Fail Offside Rear Fluid suspension unit leaking (2.4.D.2)

Advice Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #2 2006-09-14 13:32

**MOT test number** 520767656231

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2006-04-24 12:30

MOT test number 130604016195

**Result** 
✓ Passed

**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	


Type

Damage 2

Date

Category

**Type** 



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	
***************************************	
***************************************	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	IK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



19JAY

report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-04-30
Last registration	2023-04-20
Complete history	See info



Registration #1	2002-04-30	18 mi
Registration #2	2006-04-24	26.735 mi
Registration #3	2006-09-14	27.560 mi
Registration #4	2007-09-28	27.821 mi
Registration #5	2007-10-05	27.822 mi
Registration #6	2010-10-05	31.050 mi
Registration #7	2011-09-30	34.567 mi
Registration #8	2012-10-24	36.141 mi
Registration #9	2013-10-11	38.161 mi
Registration #10	2013-10-21	38.175 mi
Registration #11	2014-10-16	40.002 mi
Registration #12		71.777 es
Registration #13		9.377 es
Registration #14		11.777 es
Registration #15		0.07 m
Registration #16		11.777 es
Registration #17		9.777 es
Registration #18		11.777 es
Registration #19		9.77 es
Registration #20		71.777 es
Registration #21		11.777 es
Registration #22		71.777 es

More info >

CarCheck.co.uk page 12/13



		_		
I ) I m	ension	c l	MOIG	nt.
	CHSIUH	3 W	welu	III.

Width	1982 mm
Height	1288 mm
Length	4499 mm
Wheel base	2515 mm
Kerb weight	1845 kg

## Additional information

Fuel tank capacity	80 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11396330366707

CarCheck.co.uk page 13/13