





report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LL29 SPORT DCI
Colour	Silver
Year of manufacture	2012
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	37.2 mpg
CO2 emission	190 g/km
CO2 label	



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date	2022-03-02	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-05-08
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	24
Total items failed	6

MOT #11	2024-04-18 14:08
MOT test number	426579444605
Result	✓ Passed
Next expiry date	2025-05-08

MOT #10	2024-04-18 08:31
MOT test number	510614064469
Result	X Failed
Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #9		2023-05-09 12:07
MOT test	number	406448283010
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Passenger seat(s) missing at time of test 3rd row	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #8	2023-04-20 09:10
MOT test number	643126792820
Result	× Failed
Advice Offside Rear Seat belt buckle slightly damaged 3rd row (7.1.2 (d))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.	3 (e))
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2	2.3 (d) (ii))
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2	.3 (d) (ii))
Fail Central Rear Seat belt retracting mechanism defective 3rd row (7.3	1.2 (e))
Advice Nearside Rear Nail in tyre	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3	3 (d) (ii))

MOT #7	2022-01-24 15:54
MOT test number	145003916906
Result	✓ Passed
MOT #6	2018-10-26 12:27
MOT to at mumber	277515100240

MOT test number 377515100249 Result ✓ Passed Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Play in steering rack inner joint(s) Minor Offside Rear Window damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #5 2018-10-17 10:37 **MOT** test number 139024289682 Result × Failed **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Minor Offside Rear Window damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Minor **Advice** Nearside Front Play in steering rack inner joint(s) **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #4	2017-09-29 15:18
MOT test number	709904750016
Result	✓ Passed

MOT #3	2017-09-28 14:50
MOT test number	304999801267
Result	× Failed
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #2	2016-09-01 14:07
MOT test number	451101867777
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1

MOT test number

827807317625

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/13



DG62TPF report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	8 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

DG62TPF

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. about of pliates

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-10-18
Last registration	2024-04-18
Complete history	See info



Registration #1	2012-10-18	25 mi
Registration #2	2015-09-17	16.950 mi
Registration #3	2016-09-01	24.506 mi
Registration #4	2017-09-28	32.440 mi
Registration #5	2017-09-29	32.440 mi
Registration #6	2018-10-17	44.306 mi
Registration #7	2018-10-26	44.439 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	1904 mm
Height	1954 mm
Length	5182 mm
Kerb weight	1907 kg
Max. allowed weight	3055 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2
Engine number	C016689

CarCheck.co.uk page 13/13