





General information

Make	RENAULT
Model	MODUS DYNAMIQUE 16V
Colour	Red
Year of manufacture	2005
Top speed	114 mph
0 - 60 mph	12.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	150 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	185 g/km
CO2 label	I







Internet history

Entry 2	
Date	2022-09-02
Pictures	22
Listing price	View report









source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-11-21

18

View report



source: cargurus.co.uk









MOT history

MOT expiry date	2024-09-05
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	45
Total items failed	26

MOT #23		2023-08-15 15:36
MOT test	number	999343379929
Result		✓ Passed
Next expi	ry date	2024-09-05
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.1	.1 (c))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice (ii))	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened in	nner side (1.1.14 (a)
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	





MOT #22 2023-08-15 10:19
MOT test number 991320204615
Result × Failed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
FailNearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b)(ii))
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))
Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner side (1.1.14 (a) (ii))
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
FailOffside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b)(ii))
Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #21	2022-08-23 11:50
MOT test number	409424467183
Result	✓ Passed



	report date: 2024-03-28
MOT #20	2022-08-22 12:58
MOT test number	449197094458
Result	🗙 Failed
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	

VK55PYI

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #19		2021-09-06 09:44
MOT test	number	875424588690
Result		✓ Passed
Advice	Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))	

MOT #18	2021-09-06 07:22
MOT test number	897828792293
Result	🗙 Failed
Fail Offside Rear Direction indicator adversely affected by the operation of another la	mp (4.4.3 (b))
Advice Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))	
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Oil leak, but not excessive engine (8.4.1 (a) (i))	





MOT #17	2020-06-24 13:47
MOT test number	383994513641
Result	Passed
Minor Nearside Obligatory mirror slightly loose mirror body inseure (3.3 (b) (i))	
Advice Slight engine oil leaks	
Advice Offside Front inner track rod ball joint has slight play	

MOT #16	2020-03-17 08:53
MOT test number	925427788822
Result	🗙 Failed
Advice Both front tyres perished	
Fail Position lamp switch does not operate in accordance with the requirements (4.2.2	(a))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Inner Steering linkage ball joint has excessive play rack joint (2.1.3 (b)	o) (i))
Advice Oil leak from engine	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail Emissions not tested major missfire (8.2.1.2 (d))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
FailNearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingre(ii))	ess of dirt (5.3.4 (b)

MOT #15	2019-04-12 07:15
MOT test number	420712022893
Result	✓ Passed
MOT #14	2018-03-09 14:44

MOT test number	922748062978
Result	✓ Passed





MOT #13	2017-03-24 12:31
MOT test number	402607000812
Result	✓ Passed
Advice Slight oil leak	
Advice Nearside front tyre heavily worn outer edge	
Advice Passenger front door dropped slightly	
NOT #12	
MOT #12	2016-04-25 15:13
MOT test number	637617882378
Result	✓ Passed
Advice Both front wiper blades torn	
Advice Oil leak	

MOT #11	2016-04-19 15:52
MOT test number	405472927716
Result	× Failed
Fail Offside Front coil spring broken (2.4.C.1a)	
Advice Both front wiper blades torn	
Advice Oil leak	
Fail Nearside Front Outer Front constant velocity joint gaiter insecure to the extent prevents the ingress of dirt etc (2.5.C.1a)	that it no longer
MOT #10	2015-03-31 11:08

MOT test	number	719080095081
Result		✓ Passed
Notice	Spare wheel insecure loose in winch cable	





MOT #9	2015-03-30 12:33
MOT test number	629619685099
Result	🗙 Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside Front Tyre has a cut in excess of the requirements deep enough to a	reach the ply or cords
(4.1.D.1a)	
Notice Spare wheel insecure loose in winch cable	
Fail Nearside Front constant velocity joint gaiter insecure to the extent that it no	o longer prevents the
ingress of dirt etc (2.5.C.1a)	
Fail Offside Front Tyre has a tear, caused by separation or partial failure of its st	tructure (4.1.D.1b)
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #8		2014-03-24 11:27
MOT test	number	696483784036
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Engine warning light on	

MOT #7	2013-04-15 15:25
MOT test number	648135603192
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #6		2012-04-20 13:56
MOT test	number	265071612462
Result		✓ Passed
Notice	Offside rear brake bind	
Notice	Front brake pads wearing thin	
Notice	Offside rear tyre wearing thin	





MOT #5		2011-04-20 11:59
MOT test number		967320911112
Result		✓ Passed
MOT #4		2011-04-20 11:59
MOT test number		276330211177
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
Pass with rectification	Offside Headlamp aim too low (1.8)	

MOT #3		2010-04-15 10:47
MOT test	number	130765000134
Result		✓ Passed
Notice	Rear brake pads and discs worn/corroded/binding	

2009-04-22 15:45
290912919143
✓ Passed

MOT #1	2008-08-06 15:22
MOT test number	260499818281
Result	✓ Passed
Notice Front wipers worn slightly	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 5 September 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	5 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damaye 2	e cut of
Date	St.
Category	AMP
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

NUMBER OF CONTRACTOR OF CONTRA	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-09-24
Last registration	2023-08-15
Complete history	<u>See info</u>



Registration #2 2008-08-06 17.757 m Registration #3 2009-04-22 20.864 m Registration #4 2010-04-15 25.422 m Registration #5 2011-04-20 30.204 m Registration #6 2012-04-20 34.226 m Registration #7 2013-04-15 38.361 m Registration #8 2014-03-24 43.932 m Registration #9 2015-03-30 48.834 m Registration #10 2015-03-31 48.834 m Registration #11 2016-04-19 53.694 m Registration #12 2016-04-25 53.735 m Registration #13 2017-03-24 57.645 m			
Registration #3 2009-04-22 20.864 mt Registration #4 2010-04-15 25.422 mt Registration #5 2011-04-20 30.204 mt Registration #6 2012-04-20 34.226 mt Registration #7 2013-04-15 38.361 mt Registration #7 2013-04-15 38.361 mt Registration #7 2013-04-15 38.361 mt Registration #8 2014-03-24 43.932 mt Registration #9 2015-03-30 48.834 mt Registration #10 2015-03-31 48.834 mt Registration #11 2016-04-19 53.694 mt Registration #12 2016-04-25 53.735 mt Registration #13 2017-03-24 57.645 mt Registration #14 E E Registration #15 E E Registration #16 E E Registration #17 E E Registration #18 E E Registration #19 E E Registration #20 E E Registration #21 E E Registration #23 </th <th>Registration #1</th> <th>2005-09-24</th> <th>29 mi</th>	Registration #1	2005-09-24	29 mi
Registration #4 2010-04-15 25.422 m Registration #5 2011-04-20 30.204 m Registration #6 2012-04-20 34.226 m Registration #7 2013-04-15 38.361 m Registration #7 2013-04-15 38.361 m Registration #8 2014-03-24 43.932 m Registration #9 2015-03-30 48.834 m Registration #10 2015-03-31 48.834 m Registration #11 2016-04-19 53.694 m Registration #12 2016-04-25 53.735 m Registration #13 2017-03-24 57.645 m Registration #14 Image: Stration #14 Image: Stration #15 Registration #15 Image: Stration #16 Image: Stration #17 Registration #18 Image: Stration #19 Image: Stration #16 Registration #19 Image: Stration #20 Image: Stration #20 Registration #21 Image: Stration #21 Image: Stration #21 Registration #23 Image: Stration #24 Image: Stration #24	Registration #2	2008-08-06	17.757 mi
Registration #5 2011-04-20 30.204 mt Registration #6 2012-04-20 34.226 mt Registration #7 2013-04-15 38.361 mt Registration #8 2014-03-24 43.932 mt Registration #8 2014-03-24 43.932 mt Registration #9 2015-03-30 48.834 mt Registration #10 2015-03-31 48.834 mt Registration #11 2016-04-19 53.694 mt Registration #12 2016-04-25 53.735 mt Registration #13 2017-03-24 57.645 mt Registration #14 T T Registration #15 T T Registration #16 T T Registration #17 T T Registration #18 T T Registration #20 T T Registration #21 T T Registration #22 T T Registration #23 T T Registration #24 T T	Registration #3	2009-04-22	20.864 mi
Registration #6 2012-04-20 34.226 m Registration #7 2013-04-15 38.361 m Registration #8 2014-03-24 43.932 m Registration #8 2015-03-30 48.834 m Registration #9 2015-03-30 48.834 m Registration #10 2015-03-31 48.834 m Registration #10 2016-04-19 53.694 m Registration #11 2016-04-25 53.735 m Registration #12 2016-04-25 53.735 m Registration #13 2017-03-24 57.645 m Registration #14 T T Registration #15 T T Registration #16 T T Registration #17 T T Registration #19 T T Registration #20 T T Registration #21 T T Registration #23 T T Registration #24 T T	Registration #4	2010-04-15	25.422 mi
Registration #7 2013-04-15 38.361 m Registration #8 2014-03-24 43.932 m Registration #9 2015-03-30 48.834 m Registration #10 2015-03-30 48.834 m Registration #10 2015-03-31 48.834 m Registration #10 2016-04-19 53.694 m Registration #11 2016-04-25 53.735 m Registration #13 2017-03-24 57.645 m Registration #14 Image: Stration #14 Image: Stration #15 Registration #16 Image: Stration #16 Image: Stration #17 Registration #19 Image: Stration #19 Image: Stration #10 Registration #20 Image: Stration #20 Image: Stration #20 Registration #21 Image: Stration #23 Image: Stration #23 Registration #24 Image: Stration #24 Image: Stration #24	Registration #5	2011-04-20	30.204 mi
Registration #8 2014-03-24 43.932 m Registration #9 2015-03-30 48.834 m Registration #10 2015-03-31 48.834 m Registration #10 2016-04-19 53.694 m Registration #11 2016-04-25 53.735 m Registration #12 2016-04-25 53.735 m Registration #13 2017-03-24 57.645 m Registration #14 Image: Stration #15 Image: Stration #16 Registration #15 Image: Stration #16 Image: Stration #17 Registration #18 Image: Stration #18 Image: Stration #19 Registration #20 Image: Stration #20 Image: Stration #20 Registration #21 Image: Stration #23 Image: Stration #23 Registration #24 Image: Stration #24 Image: Stration #24	Registration #6	2012-04-20	34.226 mi
Registration #9 2015-03-30 48.834 m Registration #10 2015-03-31 48.834 m Registration #10 2015-03-31 48.834 m Registration #11 2016-04-19 53.694 m Registration #12 2016-04-25 53.735 m Registration #13 2017-03-24 57.645 m Registration #14	Registration #7	2013-04-15	38.361 mi
Registration #10 2015-03-31 48.834 m Registration #11 2016-04-19 53.694 m Registration #12 2016-04-25 53.735 m Registration #13 2017-03-24 57.645 m Registration #14 1000000000000000000000000000000000000	Registration #8	2014-03-24	43.932 mi
Registration #11 2016-04-19 53.694 m Registration #12 2016-04-25 53.735 m Registration #13 2017-03-24 57.645 m Registration #14	Registration #9	2015-03-30	48.834 mi
Registration #122016-04-2553.735 mRegistration #132017-03-2457.645 mRegistration #14Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #10	2015-03-31	48.834 mi
Registration #132017-03-2457.645 mRegistration #14	Registration #11	2016-04-19	53.694 mi
Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #12	2016-04-25	53.735 mi
Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #13	2017-03-24	57.645 mi
Registration #16Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #14		11.777 esi
Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #15		11.222 esi
Registration #18Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #16		11.777 esi
Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #17		11.777 esi
Registration #20 Registration #21 Registration #22 Registration #23 Registration #24	Registration #18		11.777 est
Registration #21 Registration #22 Registration #23 Registration #24	Registration #19		11.777 esi
Registration #22 Registration #23 Registration #24	Registration #20		11.777 est
Registration #23 Registration #24	Registration #21		11.777 esi
Registration #24	Registration #22		11.377 est
	Registration #23		11.777 mi
Registration #25	Registration #24		11.777 est
	Registration #25		11.777 esi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1960 mm
Height	1589 mm
Length	3792 mm
Wheel base	2482 mm
Kerb weight	1205 kg
Max. allowed weight	1695 kg
Additional information	
Fuel tank capacity	49
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 16/16

Number of axles	2
Engine number	D010100