





report date: 2024-03-29

General information

Make	BMW
Model	525 525D SE
Colour	Black
Year of manufacture	2004
Top speed	143 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	177 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.497 сс
Cylinders	6
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	179 g/km
CO2 label	1



CarCheck.co.uk page 1/17




report date: 2024-03-29

Internet history

Entry 2


Date	2023-02-25	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

Entry 1

Date	2021-10-14	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

CarCheck.co.uk page 2/17



report date: 2024-03-29

MOT history

MOT expiry date	2023-03-20
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	64
Total items failed	14

MOT #21		2022-03-21 16:08
MOT test	number	911649366041
Result		✓ Passed
Next expi	ry date	2023-03-20
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Advice Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii))	
Advice	Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both side	(1.1.14 (a) (ii))

CarCheck.co.uk page 3/17



report date: 2024-03-29

MOT #20 2022-03-21 14:24

MOT test number 913498130031

Result X Failed

MAJOR Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #19 2020-12-15 11:32

MOT test number 805660330652

Result

Passed

Advice Suspension arm pin or bush worn but not resulting in excessive movement ns and os (5.3.4 (a) (i))

CarCheck.co.uk page 4/17



report date: 2024-03-29

MOT #18 2020-11-19 09:56

MOT test number 198226211408

Result × Failed

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Hand brake needs adjustment

MAJOR Offside Rear Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Offside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Nearside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #17 2019-11-19 16:29

MOT test number 354402050627

Result \(\sqrt{Passed} \)

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #16 2018-11-10 12:58

MOT test number 956635233026

Result
✓ Passed

CarCheck.co.uk page 5/17



report date: 2024-03-29

MOT #15 2017-11-20 14:30 **MOT test number** 479980848380 Result ✓ Passed **Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c) Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Advice Child Seat fitted not allowing full inspection of adult belt Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Rear Brake pipe slightly corroded (3.6.B.2c) Advice Oil leak

MOT #14	2017-11-18 11:19
MOT test number	904015834286
Result	× Failed
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Child Seat fitted not allowing full inspection of adult belt	
Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)	
Advice Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice Oil leak	
Fail Parking brake: efficiency below requirements (3.7.B.7)	

CarCheck.co.uk page 6/17



report date: 2024-03-29

MOT test number

Result

Advice Front tyres wearing on edges

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #12 2016-09-29 19:03 **MOT** test number 330475471781 Result × Failed Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2) Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2) Fail Offside Front Headlamp aim too low (1.8) **Advice** Front Bumper insecure Fail Horn not working (1.6.2a) Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c) Advice Front tyres worn on edges Advice Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4,G.2)Parking brake: efficiency below requirements (3.7.B.7) Fail Advice Nearside Front Nail in tyre Fail Offside Front Headlamp insecure (1.7.3) **Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

 MOT #11
 2014-05-01 11:16

 MOT test number
 278211024483

 Result
 ✓ Passed

CarCheck.co.uk page 7/17



report date: 2024-03-29

MOT #10

MOT test number

915262814118

Result

Fail Horn not working (1.6.2a)

Fail Passenger's airbag obviously defective (5.4.1)

MOT test number

Result

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

 MOT #8
 2013-05-01 13:15

 MOT test number
 726151123181

 Result
 ✓ Passed

MOT test number

687982803153

Result

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Notice Front and rear brake discs showing signs of wear

CarCheck.co.uk page 8/17



report date: 2024-03-29

MOT test number

Result

Notice Seat belt tensioner warning lamp on

Notice Air bag warning lamp on

Notice Run flat tyre warning lamp on

Notice N/s/f tyre cut on outer wall

MOT #5		2011-04-06 14:54
MOT test	number	495866791010
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Notice	Rear brake discs corroded.	
Advice	Nearside Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Brake pipe slightly corroded (3.6.B.2c)	

MOT #4	2010-04-06 09:34
MOT test number	174666390417
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 9/17



report date: 2024-03-29

MOT #3	2009-03-30 13:15
MOT test number	431759989049
Result	✓ Passed
MOT #2	2008-04-08 14:48
MOT test number	653249498008
Result	✓ Passed
MOT #1	2007-11-09 09:18
MOT test number	392593517385
Result	✓ Passed
Notice Airbag warning light on.	
Notice Front number plate cracked.	

CarCheck.co.uk page 10/17



RF54MDZ report date: 2024-03-29

Tax & MOT check



Tax expired:
31 January 2022

X MOT

Expired: 20 March 2023

Tax status	Expired at 31 January 2022
Days left	819 days too late
MOT expiry date	20 March 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 11/17



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this BMW? How many owners declared the current and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info

CarCheck.co.uk page 14/17



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 15/17



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-11-02
Last registration	2022-03-21
Complete history	See info



Registration #1	2004-11-02	13 mi
Registration #2	2007-11-09	52.890 mi
Registration #3	2008-04-08	58.381 mi
Registration #4	2009-03-30	67.114 mi
Registration #5	2010-04-06	72.115 mi
Registration #6	2011-04-06	76.660 mi
Registration #7	2012-04-13	84.121 mi
Registration #8	2013-04-12	88.953 mi
Registration #9	2013-05-01	89.157 mi
Registration #10	2014-02-20	91.702 mi
Registration #11	2014-04-22	91.797 mi
Registration #12	2014-05-01	91.797 mi
Registration #13		11.777 mi
Registration #14		11.777 es
Registration #15		11.777 mi
Registration #16		11.777 es
Registration #17		11.777 mi
Registration #18		11.777 es
Registration #19		11.777 mi
Registration #20		11.777 es
Registration #21		
Registration #22		11.777 46
Registration #22 Registration #23		11.777 es

More info >



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1469 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1660 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Engine number	33485614

CarCheck.co.uk page 17/17