



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ASTRA SRI VX-LINE NAV S/S
Colour	White
Year of manufacture	2018
Top speed	146 mph
0 - 60 mph	6.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	300 Nm at 1.700 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	142 g/km
CO2 label	F





Internet history


Entry 2

Date	2021-08-27
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 1

Date	2021-08-26
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-07
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	9
Total items failed	2

MOT #7	2024-04-03 11:45
MOT test number	774754700416
Result	✓ Passed
Next expiry date	2025-04-07
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2024-04-03 11:45
MOT test number	439049682106
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #5	2023-04-05 11:26
MOT test number	819606318824
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2023-04-05 11:26**MOT test number** 883380864576**Result** ✗ Failed**Pass with rectification** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))**MOT #3** 2022-04-06 13:37**MOT test number** 206607568619**Result** ✓ Passed**MOT #2** 2021-04-08 15:52**MOT test number** 234067965400**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #1** 2021-04-08 12:13**MOT test number** 675442327561**Result** ✗ Failed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 April 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	7 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 MJ18XPP
Plate since	2019-06-29
Current registration	 MJ18XPP
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-05-16
Last registration	2024-04-03
Complete history	See info



Registration #1	2018-05-16	17 mi
Registration #2	2021-04-08	9.502 mi
Registration #3	2021-04-08	9.503 mi
Registration #4	2021-04-08	9.503 mi
Registration #5	2021-04-08	9.503 mi
Registration #6	2021-04-08	9.503 mi
Registration #7	2021-04-08	9.503 mi
Registration #8	2021-04-08	9.503 mi
Registration #9	2021-04-08	9.503 mi
Registration #10	2021-04-08	9.503 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	83%
Safety systems	75%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2042 mm
Height	1485 mm
Length	4370 mm
Wheel base	2662 mm
Kerb weight	1275 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B1180226DPZX0320LWC