



report date: 2024-03-29

General information

Make	FIAT
Model	500 C C POP
Colour	White
Year of manufacture	2010
Top speed	113 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	131 Nm at 4.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 2


Date	2023-11-30
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-13
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-11-28
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	36
Total items failed	10

MOT #19	2023-11-29 17:29
MOT test number	445700951683
Result	✓ Passed
Next expiry date	2024-11-28

MOT #18	2023-11-29 15:51
MOT test number	903471196822
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge wearing on inner tread area. (5.2.3 (e))

MOT #17	2023-08-15 12:17
MOT test number	211994578754
Result	✓ Passed
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16	2022-08-12 16:08
MOT test number	562295787254
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Boot not opening from outside.

**MOT #15** 2022-08-12 13:15**MOT test number** 395108566250**Result** ✗ Failed**Fail** Brake performance not tested Due to the condition of the flexi pipe o/s/f. (1.2.1 (g))**Advice** Boot not opening from outside.**Fail** Offside Front Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))**MOT #14** 2021-08-16 15:47**MOT test number** 542778669000**Result** ✓ Passed**MOT #13** 2021-08-16 14:27**MOT test number** 361864010322**Result** ✗ Failed**Fail** Offside Front Shock absorbers has negligible damping effect (5.3.2 (d))**Pass with rectification** Nearside Rear Brake cable insecure (1.1.15 (c))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #12** 2021-01-04 14:17**MOT test number** 857301535113**Result** ✓ Passed**MOT #11** 2020-01-09 13:19**MOT test number** 752955529401**Result** ✓ Passed

**MOT #10** 2019-09-24 13:37**MOT test number** 614143131141**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear exhaust outer casing corroded**MOT #9** 2018-09-26 08:31**MOT test number** 433720364772**Result** ✓ Passed**Advice** Offside Rear Shock absorbers has a slightly worn bush top bush (5.3.2 (c))**Advice** Offside Front Suspension component pin or bush slightly worn lower arm rear bush (5.3.4 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Suspension component pin or bush slightly worn lower arm rear bush (5.3.4 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #8** 2017-09-18 13:52**MOT test number** 649268171970**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

**MOT #7** 2016-09-26 10:35**MOT test number** 588893875410**Result** ✓ Passed**Advice** OFFSIDE REAR TYRE IS CRACKED IN TREAD AREA**Advice** REAR EXHAUST IS CORRODED**MOT #6** 2015-09-17 11:25**MOT test number** 218798591051**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** O/S/R tyre tread cracked**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-09-17 09:20**MOT test number** 561302685772**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** O/S/R tyre tread cracked**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2014-09-24 14:52**MOT test number** 157147464283**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** O/S/R tyre tread cracking**MOT #3** 2014-09-24 12:46**MOT test number** 358027264414**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** O/S/R tyre tread cracking**MOT #2** 2013-09-28 10:47**MOT test number** 495891473200**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-09-28 10:47**MOT test number** 327691673288**Result** ✗ Failed**Pass with rectification** Nearside Brake cable insecure (3.5.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
28 November 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-09-30
Last registration	2023-11-29
Complete history	See info



Registration #1	2010-09-30	10 mi
Registration #2	2013-09-28	18.651 mi
Registration #3	2014-09-24	23.275 mi
Registration #4	2014-09-24	23.275 mi
Registration #5	2015-09-17	27.755 mi
Registration #6	2015-09-17	27.755 mi
Registration #7	2016-09-26	29.931 mi
Registration #8	2017-09-18	31.086 mi
Registration #9	2018-09-26	32.231 mi
Registration #10	2019-09-24	33.886 mi
Registration #11	2020-01-09	34.139 mi
Registration #12	2020-01-09	34.139 mi
Registration #13	2020-01-09	34.139 mi
Registration #14	2020-01-09	34.139 mi
Registration #15	2020-01-09	34.139 mi
Registration #16	2020-01-09	34.139 mi
Registration #17	2020-01-09	34.139 mi
Registration #18	2020-01-09	34.139 mi
Registration #19	2020-01-09	34.139 mi
Registration #20	2020-01-09	34.139 mi
Registration #21	2020-01-09	34.139 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	970 kg
Max. allowed weight	1385 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	1581124