





report date: 2024-03-29

General information

Make	PEUGEOT
Model	EXPERT HDI 1000 L1H1 PROFESSIONAL P/V
Colour	Silver
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-30

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-09-28
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	8
Total items failed	17

MOT #9	2023-09-29 12:37
MOT test number	598988102341
Result	✓ Passed
Next expiry date	2024-09-28
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #	3	2023-09-23 13:05
MOT te	st number	992991784208
Result		× Failed
Fail	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail	Offside Headlamp not working on main beam (4.1.1 (a) (ii))	
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7	7.1 (b) (ii))
Advic	e Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		prevents the ingress
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #7	2022-09-23 15:00
MOT test number	168042242151
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2022-09-23 10:03 **MOT** test number 177081347541 Result × Failed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Front Headlamp aim too high (4.1.2 (a)) **Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a)) Fail Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Offside Front Headlamp aim too high (4.1.2 (a)) Fail Fail Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #5	2021-09-24 09:50
MOT test number	723578985707
Result	✓ Passed

MOT #4

MOT test number

960034067294

Result

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/12



Result

Fail

KM16CWP

report date: 2024-03-29

X Failed

MOT #3 2020-06-11 14:48

MOT test number 833157077054

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2020-06-11 11:30

MOT test number 681190981715

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #1 2019-03-28 11:14

MOT test number 772545075596

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 28 September 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	28 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
HARMAN AND AND AND AND AND AND AND AND AND A	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	IK SIN
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-31
Last registration	2023-09-29
Complete history	See info



Registration #1	2016-03-31	8 mi
Registration #2	2019-03-28	36.359 mi
Registration #3	2020-06-11	46.040 mi
Registration #4	2020-06-11	46.040 mi
Registration #5	2021-09-24	52.828 mi
Registration #6	2021-09-24	52.828 mi
Registration #7		11.777 mi
Registration #8		0.074
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 au

More info >

CarCheck.co.uk page 11/12



KM16CWP report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	1986 mm
Height	1980 mm
Length	4805 mm
Kerb weight	1814 kg
Max. allowed weight	2698 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

DYZG4158522