



**HYI3FDK**

report date: 2024-03-28

General information

Make	CITROEN
Model	DS4 E-HDI AIRDREAM DSTYLE EGS
Colour	White
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	114 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-12-07
Pictures	18
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-11-15
<b>MOT pass rate</b>	62 %
<b>MOT passed</b>	8
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	27
<b>Total items failed</b>	5

**MOT #13** 2023-11-16 13:33**MOT test number** 713199839284**Result** ✓ Passed**Next expiry date** 2024-11-15

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Offside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #12** 2023-11-16 13:33**MOT test number** 773148676469**Result** ✗ Failed

- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Offside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2022-11-16 10:51**MOT test number** 449164743064**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2021-11-08 17:00**MOT test number** 768256263041**Result** ✓ Passed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9** 2021-11-08 17:00**MOT test number** 151725888678**Result** ✗ Failed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Offside Front Road wheel more than one fixing loose (5.2.1 (a) (ii))**MOT #8** 2020-08-14 11:25**MOT test number** 885623870942**Result** ✓ Passed**MOT #7** 2019-08-13 16:39**MOT test number** 457640579634**Result** ✓ Passed

**MOT #6**

2019-08-09 08:37

**MOT test number**

823612610124

**Result****✗ Failed****Advice** Near side front link arm slightly bent**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened bothsides (1.1.14 (a) (ii))**MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps bothsides (4.7.1 (b) (ii))**MOT #5**

2018-08-06 15:04

**MOT test number**

724808571868

**Result****✓ Passed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #4**

2018-08-06 14:30

**MOT test number**

743368936702

**Result****✗ Failed****Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #3	2017-04-05 15:08
MOT test number	226675174262
Result	✓ Passed
MOT #2	2016-03-31 14:51
MOT test number	903175537774
Result	✓ Passed
MOT #1	2016-03-31 14:51
MOT test number	619251933841
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
15 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	15 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-29
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2013-03-29	9 mi
Registration #2	2016-03-31	41.601 mi
Registration #3	2016-03-31	41.601 mi
Registration #4	2017-04-05	51.103 mi
Registration #5	2018-08-06	64.170 mi
Registration #6	2018-08-06	64.170 mi
Registration #7	2019-08-09	75.853 mi
Registration #8	2019-08-13	75.853 mi
Registration #9	2019-08-13	75.853 mi
Registration #10	2019-08-13	75.853 mi
Registration #11	2019-08-13	75.853 mi
Registration #12	2019-08-13	75.853 mi
Registration #13	2019-08-13	75.853 mi
Registration #14	2019-08-13	75.853 mi
Registration #15	2019-08-13	75.853 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	83%
Pedestrian	40%
Safety systems	97%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1850 mm
Height	1508 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1430 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBFT0005332