



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI STYLE
Colour	Silver
Year of manufacture	2014
Top speed	122 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-09-08
Pictures	18
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-07
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-09
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	11
Total items failed	8

MOT #13	2023-09-11 10:07
MOT test number	799079692589
Result	✓ Passed
Next expiry date	2024-10-09
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12	2022-10-10 16:14
MOT test number	740824423642
Result	✓ Passed

MOT #11	2022-10-10 09:03
MOT test number	556388158427
Result	✗ Failed
Fail	Nearside Front Headlamp light intensity severely reduced dip beam (4.1.4 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge both sides x2 (5.2.3 (e))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #10** 2022-09-05 10:12**MOT test number** 523479066550**Result** ✓ Passed**MOT #9** 2021-09-21 12:32**MOT test number** 505798164036**Result** ✓ Passed**Advice** Offside Front drl not working**MOT #8** 2021-09-21 10:07**MOT test number** 195503177035**Result** ✗ Failed**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Offside Front drl not working**MOT #7** 2020-12-03 16:20**MOT test number** 973706229393**Result** ✓ Passed**MOT #6** 2020-12-03 12:22**MOT test number** 140701203754**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #5** 2019-06-20 08:46**MOT test number** 898276483920**Result** ✓ Passed

**MOT #4** 2019-06-20 08:46**MOT test number** 860786638860**Result** ✗ Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #3 2018-06-25 11:43**MOT test number** 764288979952**Result** ✓ Passed**MOT #2** 2018-06-25 08:30**MOT test number** 237269733491**Result** ✗ Failed

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Tpms light on

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2017-08-31 08:46**MOT test number** 515745062595**Result** ✓ Passed

Advice Both front tyres worn on tread inner and outer



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 October 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	9 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EY64YBN
Plate since	2024-03-28
Current registration	EY64YBN
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-09-01
Last registration	2023-09-11
Complete history	See info



Registration #1	2014-09-01	21 mi
Registration #2	2017-08-31	37.762 mi
Registration #3	2018-06-25	43.455 mi
Registration #4	2018-06-25	43.455 mi
Registration #5	2019-06-20	53.177 mi
Registration #6	2019-06-20	53.177 mi
Registration #7	2020-12-03	75.623 mi
Registration #8	2020-12-03	75.623 mi
Registration #9	2020-12-03	75.623 mi
Registration #10	2020-12-03	75.623 mi
Registration #11	2020-12-03	75.623 mi
Registration #12	2020-12-03	75.623 mi
Registration #13	2020-12-03	75.623 mi
Registration #14	2020-12-03	75.623 mi
Registration #15	2020-12-03	75.623 mi
Registration #16	2020-12-03	75.623 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1601 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	D4FDEU434529